

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 31 W


Iron COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 19 and 20

CORNER MONUMENT 1" Iron Pipe with 4" Brass Cap

DATE MONUMENT PLACED AND WITNESSED 9/19/60

WITNESSES TO CORNER..... 10" Aspen (1/4s NBT) N 40° E 29 Links



10" Aspen (1/4s NBT) S 42° E 23 Links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from small squared wood post in N & S E & W Fence Line in vicinity. Position checks with other corners in area.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 3/17/61
REGISTERED LAND SURVEYOR
Billy D. Buckler