Cons. 4047 Rev. 10/60

=1

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

·	T. <u>43 </u>	8. <u>31 W</u>	
		Iron	COUNTY
DESCRIPTION OF CORNER	1/4 Corner for Secs. 1	0/11	
CORNER MORNMENT 1#1 Ir	on Pipe with 4" Aluminu	n Cap	
DATE MOMMENT PLACED AN	D WITHESSED	n Forester Rose	
WITHERSES TO CORNER	9" Cedar (1/45 NHT)	N 71 W. 21 Des.	
	9* Cedar (1/48 NBT)	8 45 E. 21 Iks.	
<u>i</u>	6* Gedar (1/4S NBT)	S 24 W, 23 Iks.	
	AND		

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced from (2) two old and (1) new Wood Post which check for bearing and distance with (2) rotted cedar stumps which were original BT s. Signature tree in vicinity dates back to 1919.

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE 2/10/1966