## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T 43 NR 31 W

			-			COUNTY
DESCRIPTION	OF	CORNER	Section Corner	common to S	ectiona 7,19,	12,13
DESCRIPTION	OF	CORNER	MONUMENT_1	Pipe with 4	"_ Eress cap _	
WIT TNESSES	то	CORNER	64 Cedar - Te	at64_Link	<b>.</b>	
			6# Cedar - N	25 <u>r - 14</u> L11	₫ <b>ķ</b> #	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was pointed out to me by G. Divine, District Forester, of Crystal Falls. One original B.T. still in place, down, good condition.

Corner was placed and witnessed September 23, 1952.

SURVEYORS SEAL

SIGNED Scare C. Salar DATE 2/20/53\_
REGISTERED LAND SURVEYOR