## SURVEY &

JAN 1 3 1998

IROHI COUNT Y MICHIGAN RECEIVED FOR RECORD

_	<b>STATE</b>	-	Т	-	8
K	<b>L</b> _		1		 н

Harry L.

Surveyor's Michigan License No.

Signed by ,

97 DEC 23 PM 1: 29 L.C. Records L.7 P.152

GARY

THE STATE LAND SU

PISONI

Eile ofte LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 REGISTER OF DEEDS For corners in Iron Located In: Corner Code # T 43N R 33W 1. Public Land Survey C-9 .R⊥ R Ŕ 2. Property Controlling ŔΙ in Section R 3. Miscellaneous Property in Sec. Register of Deeds Stamp & File Number , Recorded Plat 5. Private Claims 2 Section Corner Sections 19, 20, 29, 30, T43N, R33W 3 , in a field survey on November 25 , 19 97 do hereby state Gary L. Pisoni that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned 5 in lines 1 and 2 above were in conformance with regulations and rules therefore as 6 required in the current manual of survey instructions of the United States Department of 7 the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of 8 the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, 9 re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded 11 on this certificate. 12 PEER GROUP APPROVED Description of original monument and accessories and/or subsequent restoration: Prom 12-1-97 Original corner established in 1851 by Guy H. Carleton, U.S. Deputy Surveyor. THE COUNTY REPRESENTATIVE Original Corner; Wood Post 37 lks.(24.42 feet) Original Bearing Trees; Sugar 10" S50° W White Pine 16" N55° E 20 lks.(13.20 feet) On 3-2-90, Brian R. Taavola, RLS with the Michigan Dept. of Transportation, found a 1" hexagon drill rod laying on ground which was originally set by Herbert F. Larson, Jr. Taavola reset section corner according to a survey map by H.F. Larson dated Feb., 1967. Taavola set a 40" by 3/4" Iron Pipe with a yellow plastic cap. Recorded in Land Corner Certificate L.6, Page 218, on March 23, 1990. 1990 Bearing Trees; White Pine S25° E 68.03 feet S12° W White Pine 10 84.45 feet N40°W Spruce 5' 18.10 feet N60° E White Pine 11 70.55 feet B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: No original corner evidence was recovered. Found iron pipe with plastic cap as set by Brian R. Taavola in 1990, accept the iron pipe as the best available evidence for restoring the corner position. 1990 Bearing Trees Recovered: N44° W Balsam 18.04 feet 8' 15" N55° E White Pine 70.57 feet White Pine 13" S23° E 67.91 feet S14° W White Pine 84,39 feet Corner record research on file with County Representative. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Over top of 3/4" diameter iron pipe set by Taavola, set a 2 inch diameter aluminum pipe monument, 30 inches long, flush with ground surface, with a 3 inch diameter aluminum cap stamped as follows; Iron County Remonumentation, T43N, R33W, S19, S20, S29, S30, 1997, RLS 27457. MARITHE CLEAN OF MICHIGAN Set Steel Sign Post, North, 0.76 feet from monument.

Date

November 29, 1997

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, NO. REVISES 27457 RD LAND