LAND CORNER RECORDATION CERTIFICATE

Filing Requ	irement of Act 74, Mich. P.	A. 1970
For corners in	ar en en en Stade en la Relation (Stade en la Relation en la Relat	REGISTER'S OFFICE) SS
Iron Located In:	Corner Code ##	IRON COUNTY, MICH.) 57
(County)		RECEIVED FOR RECORD THE DAY OF
		FEBRUARY AD. 19 95 AT
1. Public Land Survey T 43NR 35W		Z:4500LOCK PM, AND RECORDED IN LIBER
T <u>44N R 35W</u>	·	6 OF L.C. RECORDS
<u> </u>		ON PAGE 355 1
· <u>T</u> <u>B</u>		Mail Dethis
2. Property Controlling S T R	*	DEPUTY REGISTER OF DEEDS
in Section S T R		
3. Miscellaneous S T B		Register of Deeds Stamp & File Number
Property in Sec. S T R		
	Same and the same of the	
4. Lot No, Recorded Plat		ABCDEFGHIJKLM
5. Private Claims		2 6 5 4 4 3 2
Our stor Corner 34 3 TAAN B35W		3
Quarter Corner 34, 3, T44N, R35W		
Garage T. Dimoni	tember 13 in 94	5 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7
I. Gary L. Pisoni in a field survey on Ser do hereby certify that under requirements of P.A. 74, Michigan	A of 1970, the corner points mention	
in lines 1 and 2 above were in conformance with regulations	and rules therefore as required in	1 the 6 18 17 16 15 14 13
current manual of survey instructions of the United States De	partment of the Interior, Bureau of I	and hard the second sec
Management or by a decree of a Court of Law and/or that the co	rner points mentioned in lines 3, 4 a	ind 5 8 19 20 21 22 23 24
above were in conformance with the rules of the Michigan Boa Court of Law; established, re-established, monumented.	rd of Land Surveyors or by a Decree	014
expressed below:	re-monumented, recovered, round	10 30 29 28 27 26 25
•	and range may be recorded	11
NOTE: Not more than 4 corners, all in the same town	ratio ratige, may be recorded	12 31 32 35 36
on this certificate.		
A. Description of original monument and accessories	and/or subsequent restoration	
A. Description of original monument and accessories	and/or subsequent restoration.	
Original corner established by Wil	lliam A. Burt. U.S Dep	uty Surveyor in 1847.
Original corner: Fir Post		
Original bearing trees:		
Yellow Birch	18" N 31°E	59 links (38.94 feet)
Yellow Birch	12" N 42°W	36 links (23.76 feet)
TOTTOW DIT OIL		
	•	
B. Description of corner evidence found and/or method	od applied in restoring or reesta	ablishing corner:
No evidence of original corner or	bearing tree remains.	Corner position found marked
by a 5/8" x 17" rebar, set by Ger.	ald W. Carlson RLS #24	589 from a section sub-division
of Section 3. Corner set by sing	le proportionate meaur	ement and on line between the
Northwest and Northeast section c	orners of Section 3.	Set an aluminum pipe monument
over the top of rebar pin as desc	ribed below. Monument	is 3" above ground surface.
•		
This corner is accepted as the be	st available evidence	of the position of the original
corner.		
County Record Research on file wi	th County Representati	ves Office. PEER GROUP APPROVED
		Then Samy S. Risar
	·	COUNTY REPRESENTATIVE
		enting the position of the corner #P 1/-30-94
C. Description of monument for corner and accessori	es established to perpetuate to	catting the position of the corner.
At the corner position, I set a 2	diameter by 30" long	split base aluminum pipe
monument with a 3" cast aluminum	cap, stamped to read:	Iron County Remonumentation,
T44N. R35W. 1/4, S-34, S-3, T43N,	1994, RLS- 27457 from	which I established the
following new blazed and scribed	bearing trees: (all m	neasurements taken to a nail
in side of tree)		
Aspen (existing)	7" S 82°W	44.70 feet OF MICHIGAN
Aspen	8" S 49°W	64,04 feet
Aspen	8" S 67°W	65.10 feet
Aspen	6" N 73 ^O W	45.72 fee PISON
Steel Sign Post	North	1,11 feet LAND SURVEYOR
	i i	No.
A = 0		27457
Signed by Sauy L. Prome	Date/	-9-95
·		THEO LAND
Surveyor's Michigan License No. 27457		FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS 28, 1971