STATE OF MICHIGAN DEPARTMENT NATURAL RESOURCES

LAND CORNER RECORD

			Iron	COUNTY
		T	44-45N	R
DESCRIPTION OF CORNER	1/4 corner between Sections	3 & 3	4	
CORNER MONUMENT	Cross (+) chiseled on boulde	er		
DATE MONUMENT PLACED AND	WITNESSED October 9, 1968	3		
WITNESSES TO CORNER	. Sugar Maple 9 S43°W 28	lks.	*1/4 S	NBTH
N	Sugar Maple 7 N68°E 45	lks.	*1/4 S	NBT#
3	1" I.D. x 36" iron pipe will links South of corner. AND	ith 4*	aluminum	cap placed 2.00
CIRCLE CORNER REGISTER	RED			

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner re-established by proportionate measurement between Section Corners 40.23 chains to East and West. Found no visible evidence of the original corner monument or its accessories or of any replacement monument or accessories. Found evidence of an old line on old tree blazes east of corner.

Corner is on NW side of a steep hardwood ridge. The original field notes do not indicate the corner as being on a boulder, but the circumstances of proportionate measurements, in this case, caused the corner to fall as noted above.

Variation at this corner is about 7000 East. There is considerable local variation in this area.

SURVEYOR'S SEAL

SIGNED

REGISTERED LAND SURVEYOR DATE 3/19/69

DISTRIBUTION:

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing