## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

	Iron-Dickinson COUNTY
	T 44N R 30-31 W
DESCRIPTION OF CORNER North 1/16 corner between Section	ons 7 and 12
CORNER MONUMENT 1" I.D. x 36" iron pipe with 4" a	luminum cap
DATE MONUMENT PLACED AND WITNESSED August 20, 1969	
VITNESSES TO CORNER Aspen 6 S40W (mag.) 1	$\frac{1}{2}$ lks. "1/16S, BT"
Balsam 7 S792 W (mag.) 5	5½ lks. *1/16S, BT"
AND	
CIRCLE CORNER REGISTERED	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner established on line between section corner 19.973 chains north and 1/4 corner 19.973 chains south. No evidence that the corner had been previously established. Variation at this corner is 0°20'W.

SURVEYOR'S SEAL

SIGNED

REGISTERED LAND SUPPEYOR

Arthur O. Enger

DATE February 22, 1972

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor

Forestry Div., Lansing

R 4047 Rev. 10/68