## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

Iron

COUNTY

R 4047 Rev. 1/72

	T 44N R 32W
DESCRIPTION OF CORNERCenter of Se	ection 5
CORNER MONUMENT 1" I.D. x 36" iron pipe with 4" aluminum cap.	
DATE MONUMENT PLACED AND WITNESSED	March 13, 1972
WITNESSES TO CORNER Balsam 6	S40°W (mag.) 28.3 ft. "1/4S, NBT"
N	N55°W (mag.) 14.0 ft. "1/4S, NBT"
AND	
CIRCLE CORNER REGISTERED	
DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.	
No evidence that the corner had been previously established. First measured all exterior lines of Sec. 5 and re-established the section and 1/4 section corners. Then established center of section on true N & S 1/4 line at calculated intersection with E & W 1/4 line.	
Variation at this corner is 0°00°.	
SURVEYOR'S SEAL	
DISTRIBUTION:  SIGNED REGI	STERED LAND SURVEYOR orthur O. Enger
Forestry Division, Lansing	
District Forester	

District Surveyor