

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Iron
(County)

	Located in:	Corner Code is
1. Public Land Survey	T <u>44N</u> R <u>R32W</u>	<u>16</u>
	T _____ R _____	<u>75</u>
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S <u>14</u> T _____ R _____	<u>3</u>
	S _____ T _____ R _____	<u>10</u>
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

gw

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

I, Keith Sackett, in a field survey on June 14, 19 87, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below.

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2													
3													
4													
5													
6													
7													
8													
9													
10													
11													
12													
13													

A. Description of original monument and accessories and/or subsequent restoration:

<u>16</u>	<u>75</u>	<u>3</u>	<u>10</u>
Original monument and accessories not found.	Original monument and accessories not found.	Not set on original survey not subsequently, apparently.	Not set on original survey not subsequently, apparently.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

<u>16</u>	<u>75</u>	<u>3</u>	<u>10</u>
Restored midway and on line.	Restored midway and on line.	Established midway and on line.	Established midway and on line.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

<u>16</u>	<u>75</u>	<u>3</u>	<u>10</u>
Set 1" ID x 3/8" IP with 4" aluminum cap.	Set 6-14-89 1" I.D. x 3/2" I.P. with 4" aluminum cap.	Set 1" ID, 3/8" IP with 4" aluminum cap.	Set 1" ID x 3/8" IP with 4" aluminum cap.
4" white pine 802E 4.7' 1/4S, NOT	8" spruce 824W 1.3' 1/4s NOT	12" white pine 870E 1/16S, BT	16" cedar N15E 40.3 1/16S, BT
3" tanarack N40W 17.1' 1/4S, NOT	7" spruce 802E 7.0' 1/4s NOT	4" spruce 85.2' S11W 1/16S, BT	12" cedar 882N 32.0 1/16S, BT
2" tanarack N02E 14.8' 1/4S, NOT	6" spruce N24W 8.2' 1/4s NOT	4" spruce 37.4' N63W 1/16S, BT	5" balsam 871E 5.7' 1/16S, BT

Signed by Keith Sackett Date _____

Surveyor's Michigan License No. 19006

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 25, 1971
 REVISED MAY 14, 1978
 REVISED JAN., 1983