

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 44. NR. 33. W.

Iron COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 11-12-13-14

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER	10" W. Pine	S 60° E	33 links
		"S 13 NBT"	
	10" W. Pine	S 11° W	47 links
		"S 14 NBT"	
	10" W. Pine	N 51° E	10 1/2 links
		"S 12 NBT"	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Found 1 1/2" iron pipe and old wood stake at corner. Replaced Section Corner.

Two W. Pine stumps badly burned at proper position for both B.T.'s.

Corner is in line with road to east, old fence to north.

Shown to us by George Divine, District Forester.

SURVEYORS SEAL

SIGNED Billy D. Buckles DATE 3/4/52  
REGISTERED LAND SURVEYOR