LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	IRON COUNTY LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 44 N. X S., R. 33 X E. W.	D-11
2. PROPERTY CONTROLLING IN SECTION 32	,T. 44 N. X S., R. 33 X E. W.	1
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Arthur O. Enger, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on September 20, 19 78, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner D11 (1/4 corner between Sections 29 & 32, T44N, R33W):
Wood post (Not found. No subsequent monuments found.)
Y. Birch 10 S39W 52 (Not found. No subsequent accessories found.)
W. Pine 30 N25E 25 (Not found. No subsequent accessories found.)

Corner 1 (West 1/16 corner between Sections 29 & 32, T44N, R33W):
Not established in original survey nor subsequently, apparently.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner D11: Restored on line between Sec. Corners 40.1825 ch. W and 39.0685 ch. E. The uneven distances are believed to represent actual original line lengths, based on comparison of current measurements to natural features with the measurements given in the original field notes.

Corner 1: Established on line between Sec. Cor. 20.091 ch. W and 1/4 cor. 20.091 ch. E.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner D11: 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap.
Forked W. Pine 22 N 9°E (mag.) 79.2 ft. "1/4S, NBT"
Forked B. Spruce 10 S10°E (mag.) 43.7 ft. "1/4S, NBT"
Declination 1°15' East.

Corner 1: 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap.
Ironwood 8 N62°W (mag.) 10.0 ft. "1/16S, BT"
W. Pine 20 S10°W (mag.) 46.1 ft. "1/16S, BT"
Declination 1°00' East.

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY Arthur O. Enger DATE March 15, 1979
MICHIGAN REGISTERED LAND SURVEYOR

Arthur O. Enger
Michigan Department of Natural Resources

STATE OF MICHIGAN ARTHUR O. ENGER LAND SURVEYOR No 13581 REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET