## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

			-	I	[ron		COUNTY
			Т	4	5 N	_ R _	31 W
DESCRIPTION OF CORNER _	1/4 corner betw	reen Se	ctions 9 and	d 10			
CORNER MONUMENT	. D. x 36" iron	pipe	with 4" alu	mi num	cap		
DATE MONUMENT PLACED AND	WITNESSED No	vember	11, 1970				
VITNESSES TO CORNER	W. Spruce 16	N85°E	(magnetic)	22,0	feet	<b>"1/4</b> S,	NBT"
N	Balsam 7	N14°E	(magnetic)	3.5	feet	<b>"1/45,</b>	NBT"
9	AND						
CIRCLE CORNER REGISTER	ED						

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Monument placed on line between section corners 39.94 ch. to north and south. Corner lies on north-facing slope of a high ridge running ENE and WSW, about 1.00 ch. north of crest, as noted in original field notes.

Variation at this corner is about 2015 East.

SURVEYOR'S SEAL

SIGNED

REGISTERED LAND SURVEYOR

DATE July 30, 19

**DISTRIBUTION:** 

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing