STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

			Iron-Marquette COUNTY		
			T 45 N	R 30-31W	
DESCRIPTION OF CORNER North 1/16 corner between Sections 31 & 36					
CORNER MONUMENT 1.D. x 36" iron pipe with 4" aluminum cap					
DATE MONUMENT PLACED AND WITNESSED October 7, 1968					
WITNESSES TO CORNER Ba	lsam Fir 6	\$19°W 20 lks.	"1/16 S BT"		
N		West 302 lks.			
AND					
CIRCLE CORNER REGISTERED	<u> </u>				

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner established by proportionate measurement on line between Section Corner 19.98 chains North and 1/4 corner 19.98 chains South.

Found no evidence that a corner was ever established here previously.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED __

Wother O. Engar REGISTERED LAND SURVEYOR

DATE 2/14/

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047 Rev. 10/68