STATE OF MICHIGAN DEPARTMENT 0F **NATURAL RESOURCES**

LAND CORNER RECORD

	Iron	COUNTY
	T _45N	R 31-32W
DESCRIPTION OF CORNER	1/4 corner between Sections 19 and 24	
CORNER MONUMENT	1" I.D. x 36" iron pipe with 4" aluminum o	ар
DATE MONUMENT PLACED AND	WITNESSED December 16, 1968	
WITNESSES TO CORNER	. <u>Spruce</u> 8 S72°W 51 lks. *1/4 S NBT] H
N	Spruce 10 N23°E 43½ lks. *1/4 S NE	3T#
Ø19	Red Maple 6 S88°E 15 lks. "1/4 S NE	3 T#
	AND	
CIRCLE CORNER REGISTERED		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Monument placed from original BT, a W. Pine 26 N32W 43 with blaze and axe marks on stump, and a W. Pine 24 S70E 6 stump in proper position, but no marks.

Corner located by survey crew doing retracement work in T45N, R31W.

SURVEYOR'S SEAL

SIGNED

REGISTERED LAND SURVEYOR DATE 10/20/69

DISTRIBUTION:

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing