

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


Iron COUNTY  
T 45 N R 31 W

DESCRIPTION OF CORNER 1/4 corner between Sections 6 and 7

CORNER MONUMENT 1" I.D. x 36" iron pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED November 5, 1969

WITNESSES TO CORNER..... Elm 8 N5½°W (magnetic) 22 links "1/4S, NBT"



W. Spruce 8 S76½°E (magnetic) 54½ links "1/4S, NBT"

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Placed new monument at site of found cedar post. Confirmed original BT to NE by overgrowth on chopped faces. BT now down and in poor condition. BT to SW probably destroyed during logging road construction long ago.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

*Arthur O. Enger*  
REGISTERED LAND SURVEYOR  
Arthur O. Enger

DATE August 25, 1971

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68