## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

		COUNTY
		T 45 N R 31-32 W
DESCRIPTION OF CORNER	Section Corner 19, 24, 25, a	nd 30
CORNER MONUMENT1	" I.D. iron pipe with 4" alumin	um cap.
DATE MONUMENT PLACED AN	D WITNESSED May 6,	1969
ITNESSES TO CORNER	W. Spruce 13 N76°E (magnet	ic) 51 links "S19, NBT"
N	Red Maple 10 N14 W (magnet	ic) 51½ links "S24, NBT"
19	Red Maple 5 S24 W (magnet	ic) 57½ links "S25, NBT"
	AND	
CIRCLE CORNER REGISTE	RED	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Found point of rotted post in ground N44 W 21 links with Northern Paper Mills tag on nearby dead aspentree. Tag says "about Sec. Cor. B.G.B., 1942," indicating an approximate corner.

Corner placed on line between an original section corner 80.229 chains south and an original 1/4 corner 40.115 chains north.

Variation about 0°45' West.

SURVEYOR'S SEAL

SIGNED

REGISTERED LAND SURVEYOR

DATE August 27, 1971

DISTRIBUTION:

Arthur O. Enger

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing