

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


Iron COUNTY
T 45 N R 31 W

DESCRIPTION OF CORNER South 1/16 corner between Sections 9 and 10

CORNER MONUMENT 1" I. D. x 36" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED November 30, 1970

WITNESSES TO CORNER..... Cedar 8 N3½°W (magnetic) 45.2 feet "1/16S, BT"



Cedar 13 N64°E (magnetic) 39.5 feet "1/16S, BT"

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

No evidence that the corner has been previously established.

Monument placed on line between section corner 19.97 ch. south and 1/4 corner 19.97 ch. north.

Variation at this corner is about 1°30' east.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Arthur O. Enger
REGISTERED LAND SURVEYOR

DATE July 30, 1971

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68