STATE OF MICHIGAN DEPARTMENT 0F NATURAL RESOURCES

LAND CORNER RECORD

Iron

COLINTY

		000111
		T <u>45 N</u> R <u>31-32 W</u>
DESCRIPTION OF CORNER1	North 1/16 corner between Sect	ions 19 and 24
CORNER MONUMENT1"	I. D. x 36" iron pipe with 4"	aluminum cap.
DATE MONUMENT PLACED AND	MITNESSED March 16, 1970	
WITNESSES TO CORNER	Tamarack 8 N37°W (mag.) 31	.2 feet "1/16S, BT"
N	Tamarack 8 S70°E (mag.) 29	.5 feet "1/16S, BT"
	AND	
CIRCLE CORNER REGISTERE	D	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

No evidence that the corner has been previously established.

Monument placed on line between section corner 20.008 ch. north and 1/4 corner 20.008 ch. south.

Variation about 2000' west.

SURVEYOR'S SEAL

August 20, 1971
REGISTERED LAND SURVEYOR SIGNED

DISTRIBUTION:

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047 Rev. 10/68