

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


Iron COUNTY  
T 45 N R 31 W

DESCRIPTION OF CORNER Section Corner 14, 15, 22, and 23

CORNER MONUMENT 1" I. D. x 36" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED May 6, 1970

WITNESSES TO CORNER..... W. Spruce 6 N15 $\frac{1}{2}$ °W (magnetic) 75.3 ft. "S15, NBT"



B. Spruce 5 N22 $\frac{1}{2}$ °E (magnetic) 88.0 ft. "S14, NBT"

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Monument placed at an old fence corner as nearly as the intersection of old fence lines could be ascertained. Fence lines are on the N and W edges of an old field. Aerial photos support this location as about the described section corner, and distance south to river checks reasonably well, although stream bank has been altered by previous human activity.

SURVEYOR'S SEAL

SIGNED Arthur O. Enger DATE July 28, 1971  
REGISTERED LAND SURVEYOR

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68