LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

IRON COUNTY

FOR CORNERS OF -:	LOCATED IN -:	Í	CORNER CODE NUMBER	!
1. PUBLIC LAND SURVEY	n. 45 💥 R.3	1 X.	<u>C9</u>	
2. PROPERTY CONTROLL: ING IN SECTION	,T S., R	1E. W.		
3. MISCELLANEOUS PROPERTY IN SECTION -				
4. LOT NO	RDLD PLAT.	-		
5, PRIVATE CLAIMS				REGISTER OF DEEDS STAMP AND FILING NUMBER
re-established, monumented, re-n and rules therefore as required in Bureau of Land Management or h and 5 above were, in a field survey	es 1 and 2 above we commented, recover the current manual by a decree of a countern manual control of the contr	ere, in a fred or res of survey rt of law.	field survey on <u>see below</u> tored as expressed below and y instructions of the United S Furthermore, that the corner 19	of P.A. 74, Michigan P.A. of 1970,
A. Description of original monum	ient and accessories	and for si	absequent restoration:	
Corner C9: Found posin poor condition.	t and origina	l beari	ng tree, cedar 14 N50	E .22,CH tree down and
B. Description of corner evidence Corner C9: Restored				
				so rat
C. Description of monument for Corner C9: Set 1" I. 6" Spruce S52W 18.0 f 5" Spruce S77E 9.8 ft 5" Balsam N54E 6.9 ft	D. by 32" IP v t. S30, NBT S29, NBT			position of the corner:
SIGNED BY		-	DATE	
SURVEYOR'S MICHIGAN REG	ISTRATION NO.		· · · · · · · · · · · · ·	(SEAL)
FOR STATE AND UNITED ST	ATES AGENCIES:			and the second
SIGNED BY	CHIEF OF SURVEY PART	·	DATE	
APPROVED AND SIGNED BY_	MICHIGAN REG Keith L. Sad	Ckett	DATEDATE	2 /6-83 (SEAL)
SURVEYOR'S MICHIGAN REG	·	.19006	<u></u>	IRD OF REGISTRATION, JAN. 28, 1971