

SURVEY & REMONUMENTATION

Stock No. 26273

MAR 1		RNER RECORDATIO				
For corners in COM	MISSION	equirement of Act 74,	Mich. P.A. 1970		IRON COUNTY	Y
Iron	Located In:	Corner Co	ie#	REC	EIVED FUR RE	CORP
(County)					* 1	
1. Public Land Survey	T <u>46N</u> R <u>34V</u>	N C 13		30 1 1	DEC 23 AH 9	F01
1. Tubile Latia Salvey	T 445N B 434V	- Warring MC 5764 - The Art Town of Street Street		L. Kici	Records &	11, 194
	TR			يسب	illen Sie	
2. Property Controlling	TR		_	fer	The second of the second	امع ا
in Section	ST R	· · · · · · · · · · · · · · · · · · ·				
3. Miscellaneous	\$ T R			.•	i - i - i - i - i - i - i - i - i - i -	
Property in Sec.	S R	_ '	<u> </u>	Register o	Deeds Stamp &	File Number
4. Lot No, Red	orded Plat			א פ כ ה	* * C U T	
5. Private Claims	,	· · · · · · · · · · · · · · · · · · ·		1 1 1		1111
Section Corner 31 & 32,	TAGN B3AW	τ,		2 6 5	4 3	21
	T45N R34W,			3		
·	• •	;		4 - 7 - 8	910	1112
I, <u>Gary L. Pisoni</u> , in that under requirements of P				5		
in lines 1 and 2 above we				7 18-1-1	/	1413
required in the current manu	•	·		9 19 2	21 22	23 24
the Interior, Bureau of Land N corner points mentioned in li				ا ا ا		
the Michigan Board of Land	Surveyors or by a Dec	ree of a Court of Law	established,	<u> </u>	92827	26 25
re-established, monumented,	recovered, found as exp	pressed below:		11		
NOTE: Not more than 2 come	ers, all in the same town and	d range, may be recorded		12 31 3	23334	3536
on this certificate.				13		
	' i . i.					
A. Description of original m	onument and accessorie	s and/or subsequent res	storation:			
Original corner establish	ned by William A, Burt, U	S Danuty Surveyor on	Santambar 18 1	846		
Original corner: Fir Post		.o. Deputy Gurreyor or	Coptember 10, 1	040.		
Original bearing trees:	9" N 40° F	07 1:-1	- 104 40 54			
Fir Yellow Birch	9" N 40° E 12" N 73° W		s (24.42 feet) s (17.82 feet)			
Original Subdivision est	tablished by Guy H. Carle					
Original bearing trees: Yellow Birch	10" S 60° W	23 Link	s (15.18 feet)	•		
Fir	10" S 15° E		s (10.56 feet)			
B. Description of corner ev	vidence found and/or met	thad applied in restaring	nr reestablishing	comer		
•	*	aroa applica ili restornig	or recatabilaring			
No original corner evid	dence found.			DEI	ER GROUP APP M Nay J. Property DUNTY REPRESE	ROVED
Found a wood post w	hich was being used as	the corner, but post wa	s to far out of	Lize	m Say I Prom	12-11-96
	ed as the Section corner. Ial distance measured be			C	UNTY REPRESE	NTATIVE
	ial distance measured be in for restoring the corner					
between the North Qu	uarter corner of Section (6 and the North Quarter	corner of Section	n 5, T45 N R3	4W.	
Corner Record Resear	ch on file with County R	enresentative.				
				the second of		
C. Description of monum	nent for corner and acces	ssories established to pe	erpetuate locating	the position	of the corner:	
At the corner position	n, I set a 2" diameter by	30" long split base alur	ninum pipe monur	ment	and an in	Trans.
with a 3" cast aluming	um cap, stamped to read	d: Iron County Remonur	nentation, T46N,	R34W,	TE OF W	110/110
	T45N, 1996, RLS-2745 ees: (all measurements t			new blazed	GARY	1
White Spruce	12"		12.01 feet	1 p	PISO	ti.E' e 🎉 💆
White Spruce	11"	and the second s	27.04 feet	. h ' -	LAN	D 3 * 1
White Spruce Black Spruce	11" 8"	and the second s	28,14 feet 16.36 feet		SURVE)	1 6 6 7
Steel Sign Post	6'	N 07° E	1.03 feet		2745	
Wood Post #96-18 -/ a /	5" x 5" x 36"	N 80° E	35.00 feet	10 P	THE PED LAN	VD SULTER
Signed by Vary &	20 m	Date/2	-10-96	- ",	ASSESSED TVI	Richard
Surveyor's Michigan License	No. 27457	FORW	APPROVED BY MICHIGAN	I STATE BOARD OF F	ROFESSIONAL SURVEYORS	S, JAN 28, 1971
		1.7 P.40			RE	D MAY 14,1975 VISED JAN., 1983 VISED OCT., 1995
	•	, , , , , ,			REV	Price Arti" 1999