LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

	For	comers	in
--	-----	--------	----

Iron	Located In:	Corner Code #
(County)		**
1. Public Land Survey	´ T <u>46M</u> R T R T R	34N
Property Controlling In Section Miscellaneous	S_19 T_46H R S T_R S T_R	34% 10
Property in Sec.	s tR	

Register of Deeds Stamp & File Number

ABCDEFGHIJKIM

, Recorded Plat 4. Lot No. 5. Private Claims

IB Aug 05 1998 10 Aug 18 1998

L Stephan J. Szyszkoski , in a field survey on 19 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate

1	abla	<u> </u>						П				
2	_	<u>-</u>	L.,	ļ	L.,	i —	.	<u> </u>	L :	<u>!</u>	}	l —
3		Ĺ		Ĺ		Ì		Ī	[Ĩ		Ī
•					Γ			Г				
4	Η.	?—	H-1	<u> </u>	\vdash	9—	1	۰-	├ ─-1	<u>ı</u> —	<u> </u>	2—
5	_	L_	L		L.	<u> </u>		<u> </u>	_			
6	_,		L,	ا	L,	[6—	L.	<u> </u>	L.,		_,	
_	_,	ľ		ī		ì		Ī	_			_
7		\vdash	\vdash				_	-	-	_	Н	_
8	_1	_وا	2	<u>ا</u>	2	_	2	2_4	_2	ا_د'		4
) :				ĺ	Ī				Ĭ	ĺ
9				_	_			\vdash		\vdash	-	
ιo	<u></u> 3	<u>م</u>	—2 [']	9	2	8	<u>2</u>	_	2	6	_2	5_
					1			1	Ī			
11												
12	3	1	3'	2—	<u></u> _з'	3	3	4	J	5—	—3'	6
	1			i							- 1	
13	_	_	_	_				$\overline{}$				

A. Description of original monument and accessories and/or subsequent restoration:

(18) Quarter corner common to Sections 22-23. Corner established in 1852 by Zelotes B. Searles: "40.12 Set quarter section post. Cedar 12 S85M 8, do 12 East 7.° December 1953 record of Morthern Paper Mills at Med Lake Timber and Land Co. state: "1930: Cole and Sillers found 12" ced. B.T. East dead. 1953: Mickman and Peryam found post 12" Ced. E old face no I.M. Set pipe at post from Cedar. Description of corner monument: Iron pipe and brass cap. Mitnesses to corner Ced. 10 S4M 14.° Found no subsequent record. (10-Sec. 19) South 1/16 corner between Section 19 T46N-R34M and Section 24 T46N-R35M. Corner not established in the original survey. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner;

(IB) Recovered the 1953 monument as described, a 1° ID from pipe capped with a 2° brass Northern Paper Hills tablet, appropriately stamped, in good condition, and at record bearing and distance from the 1953 witness cedar, found in good condition. Scribing is visible on both upper and lower blazes. I accept the monument as a careful and faithful perpetuation of the position of the original corner. Left the monument in place and marked three new accessories as described below. Corner recovered and rewitnessed by D.tampela and B.Wheeler, Baraga District Office.

(10-Sec. 19) Found no evidence of prior monumentation at the corner position. Established the corner on a line of mean true bearing between Section corner 19.9572 ch. South and Quarter corner 19.9572 ch. Morth. At the position for the corner I placed a t° I.D. x 32° iron pipe capped with a 4" dia. cast aluminum MDMR tablet, appropriately stamped. Corner placed and witnessed by 0.Lampela and B.Wheeler, Baraga District Office.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner

are magnetic.

(18) Found i" pipe with brass NPM cap. Blazed and scribed the following: 12" Cedar N55E 31.4' 1/4S NBT 5° Tamarack S77E 19.1° ďρ 6° Tamarack N85W 7.1' do The 1953 witness:

(10) Set 1" pipe with 4" MDNR cap. Blazed and scribed the following:

8° Y. Birch NOSE 25.5' 1/16S BT 20" Hemlock NB2E 39,2" do 22" Sugar \$42E 3.0" ďο 8" Hemlock N68W 25.4" d٥ Placed a squared cedar post adjacent.

Distances are to meas, notch. Bearings

SZYSZKOSKI LAND SURVEYOR

Placed a squared cedar post north 1'. Distances are to meas, notch. Bearings

11" Cedar SOIM 9.1' marks visible,

Surveyor's Michigan License No

are magnetic. 33986

For the Michigan Department of Matural Resources - Forest Management Division