JAN 1 2 1996

CO	ñ	Á	A	А	į	C	C	ì	$\overline{}$	N	إ
	11	11	п	и.	£	$\sim$	O	ı	<b>.</b> /	1	٧

## LAND CORNER RECORDATION CERTIFICATE

IRON COUNTY
MICHIGAH
ECEIVED FOR RECORD

Fo	r corners in	Filing Requir	ement of Act 74, Mich. P.	A. 1970	RECEIVED FO	GAH OR RECORD	
	Iron (County)	Located In:	Corner Code ##		95 APR 26	AM 11: 10	
1.	Public Land Survey	т <u>46N</u> R <u>37</u> W	<u>K-5</u>		L. 6 L.C. RE		
		T R T R			Eilen	Stelie .	
		T R			REGISTER O		
2.		F R F T R	**************************************				
3.	Miscellaneous S	T R		Regis	ster of Deeds S	tamo & Eila Nu	mbar
	Property in Sec. S	T R				tomp a riie ita	
4.	Lot No, Reco	rded Plat		: .			
	Private Claims			<del></del>	ABCD	EFGHI	JKL
	Section Corner 11, 1	2, 13 & 14; 1.46N.,	, K.3/W.		3 5	-13	2
	District to Destru	, , , , , , , , , , , , , , , , , , ,	4.4		╌┡╌┼		1 2
I, _	Richard L. Drahn . in hereby certify that under requires	a field survey on <u>JUNE</u> ments of P.A. 74, Michigan P.A.	of 1970, the corner points mention	ned	5		╀┿┼╌
in I	ines 1 and 2 above were in con rent manual of survey instruction	iformance with regulations an	d rules therefore as required in	the	6 18 17	-16-15-	14
Mai	nagement or by a decree of a Cou	irt of Law and/or that the corne	er points mentioned in lines 3, 4 ar	nd 5	8 19 20	21 22	
abo Cot	ove were in conformance with the urt of Law; established, re-est	arules of the Michigan Board of tablished, monumented, re-r	of Land Surveyors or by a Decree nonumented, recovered, found	ofa i as			
exp	pressed below:			4 .	10 30-29-	-2827	26
ΝО	TE: Not more than 4 corne on this certificate.	rs, all in the same town ar	nd range, may be recorded		11		╁╼╁╾┟╴
		•			12 31 32 13 1	-33-34-	3536
Α.	Description of original mont						
	Corner established bearing trees:	y E.C. Martin, U.S.	. Deputy Surveyor, or	n July !	9, 1851. 0	riginal	
	Hemlock	12"	S.66E. 21	links	(13.86 f	eet)	
	Sugar Maple	18"	N.70W. 23 1	links	(15.18 f	eet)	
	Reference Land Corne Liber, Page J-21; on	r Certificate by Do 2/27/75 of Iron Co	onald D. Lappala, R.L	L.S. 12	585, record	ed in USFS	
	Liber, rage o zr, on	2/2///0 01 1/011 00		1 3	•	• *	
			N.				
	•			: :			
В.	Description of corner evider	nce found and/or method a	applied in restoring or reestat	blishing co	orner:	•	٠
	Reconstruction of F. After completion of	H. #16 required the the work, the corne	e removal and re-refe er was replaced as in	erencing ndicate	g of the se d below.	ction corne	er.
			· .		پ	OF MIC	<b>W</b> .
	•		· · · · · · · · · · · · · · · · · · ·	- ,		THE OF MIC	C. My
	•		PEER GROUP APPROV	V.E.IJ	*	✓ RICHARD	1.4
			IRON Day S. Room		- *	L DRAHN LAND	*
		·	COUNTY REPRESENTATI		\$ m	SURVEYOR No.	15
					<b>1</b> 1	21564	133
	Research on file wit	th County Represent	ative.		344	MAS CAND	11 1
٥.		<u> </u>	stablished to perpetuate loc	ating the p	position of the c	corner	der.
	At the corner positi	on in the blacktop	of F.H. #16 I embedd	ded a 3	" brass cap	stamped to	
	the following:	; 5-11, 5-12, 5-13	, S-14; 1994; R.L.S.	21504	Trom which	I establisi	iea
	12" S	Sugar Maple	N.82E.		52.51 feet		
		ugar Maple Sugar Maple	N.84W. N.58E.	- : :	44.00 feet 66.75 feet		
			ent bears West 70.31	5 feet	00.75 Teet		
	Aluminum capped Alum	ninum Reference Monu	ument bears East 70.3		t .	•	
	6' Steel Sign Post	East 71.32	reet	1 1			

February 7, 1995 Surveyor's Michigan License No. 21564 FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN 28, 1971 REVISED MAY 14, 1975 REVISED JAN , 1983