SURVEY & REMONUMENTATION

995 APR 2 7 1995

COMMISSION

	Was class as a first on		•	- 1-	ST	ATE ~-				
		LAND CORNER REC	f Act 74, Mich Pi	A. 1970	RECE		AREC REC	GAN LLA ORD		
	For Corners in	ISABELLA CO	UNTY REMONUMENTATION	N :	Han I	1 2				-
	Isabella		•		Mar 10 00	003	26 PH	95		
1.	(County) Public Land Survey	Located In: T <u>13 N</u> , R <u>3 V.</u> T R T R	Corner Code# <u>H-5</u>	- ·	REGIS	ON S ER OF	A BROWN DEEL	V S		
	Public Controlling in Section	S T R S T R	1	_ :						
3,	Miscellaneous Property in Sec.	S T R S T R		Register	of Dee	ds Star	np & Fil	e Nu	ı <u>mb</u> er	
4.	Lot No.	Recorded Plat		-	A B I	DE	F G H	<u>.</u>	ı K	<u>Ļ</u>
5	. Private Claims			·/ !:	2		43		}	-1 - -
					3		+		╁	-
	do hereby certify that	eld survey on December 24, t under requirements of P.A	. 74, Michigan P.A. of	1970,	4 - 7 -		910			-12-
	regulations and rules t	ioned in lines 1 and 2 above herefore as required in the	e current manual of	survey	6 -18-	17	161		ļ.	-13-
	instructions of the Unit	ted States Department of : ee of a Court of law and/c	the Interior, Bureau or that the corner p	of Land coints mentioned	7				╂┼	+
	in lines 3, 4 and 5 abov	e were in conformance with by a decree of a Court of	the rules of Michigai	n Board 🖟	8 19	20-		} - (3	-24
	monumented, re-monumen	ted, recovered, found as ex	xpressed below	C D 4 d A A A A A A A A A A A A A A A A A A	10 30-	-29	20 2		2,6	-25-
	•			·	11			_	╂	+
	NOTE: Not more than 4 on this certificat	corners, all in the same tone. e.	wn and range, may be	recorded	13 31	35	33 34		5	-36-
	A. Description of o	riginal monument and ac	ccessories and/or	r subsequent	rest	oratio	יי			
	Subdivision 3	1. survey: es Nov. 1830 by Robert Clar Brd quarter 1832 by Robert hal field notes	k t Clark	•						
	2) No subsequ	ent surveys of record by	County Surveys		:					
	3) L.C.R.C. Lib. 1, Pg. 2i Found 3/4°	01, William B. Ruddell 9/14/82 pipe	:	ACCEPTED BY REMONUMENT		eer gro	UP.			
	Found 3/4' Lib. 4, Pg. 9 Found 3/4' Lib. 5, Pg.38 Bated 8/31, Found 3/4' Lib.5, Pg. 33	Records 222, Ruddell Engineering 12/1 pipe and 2 witnesses 28, Ruddell Engineering 9/14/1 pipe and 2 witnesses same 23, Land Surveying Consultan /93 by Land Surveying Consultan pipe in Manument box 1 witnesses pipe in the Monument box w	82 nts 12/30/93 ultants iness the same nts	William B. I County Repr	luddell, P	<u>U</u>				
١	WITNESS NOTE: Witnesses presented	from above surveys and L I to peer review committee	CRC's are availiable in and is on file at the	n Dossier file, w Register of De	hich was eds Off	ice.				
	Bi Description of co or neestablishing	orner evidence found o corner: REPORT OF FINDINGS	and/or method ap	oplied in rest	oring					4
	for the cor	urvey on December 24, 1994 rner location		rched	,				. •	
	intersec	4" pipe in Monument Box at a tion Blanchard & Vroman Rd.	• -							
		3/4" pipe and Monument Box, oth of 2.8'.	, Excavated 2' diamet	er hole						

Accepted as best available evidence of the position of the original corner & replaced with Standard Monument Corner H-5 was approved for remonumentation at a Peer Review Committee meeting on November 3, 1994.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: olisheu MICHIGANA OF MICHIGAN Set standard Isabella County Monument in Monument Box

N.15*W. 60.00' stop sign post. S.42*E. 91.60' N.&C.- N. face of P.P. N.35*W. 45.65' center cable box. S.75*W. 88.23' center cable box.

Signed by

3. Found no further evidence of corner.

4. Verified position from previous surveys and L.C.R.C. of record.

Michigan License No. 21567

JAN S **FOKENS** LAND SURVEYOR
DO TON

215 FORM ABPROVEDERY MICHIGAN STATE BOARD OF LAND
SURVEYORS JON 28, 1971
REVISED MARTA, 1975
REMAISEL JAN 1983 JRVEYOR