SURVEY & REMONUMENTATION

337.60

APR 27 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

COUNT RECEIVE	OF ISABFILA
------------------	-------------

Mand Bo 335 PM '95 SHARON A BROWN REGISTER OF DEEDS

ISABELLA COUNTY REMONUMENTATION For Corners in Isabella (County) Corner Code# Located In: 1. Public Land Survey T14 N. R4 W. G-1 _ R. 2. Public Controlling in Section R 3. Miscellaneous Property in Sec.

Register of Deeds Stamp & File Number

Recorded Plat 4. Lot No. 5. Private Claims

I, Jan S. Fokens, in a field survey on December 29, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by decree of a Court of law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of Michigan Board of Land Surveyors or by a decree of a Court of Law established, re-established, monumented re-monumented recovered, found as expressed below

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restorations

- Original G.L.O. Survey:
 Township lines N. S. & E. W. 2nd quarter 1837 by John Hodgson
 Subdivision 4th quarter 1838 by R. Whitcomb
 Pg. 272 original field notes
- Subsequent survey of record by County surveyors Bk. 2, Pg. 82, May 14 & 15, 1879 by A.K. Herrington

Lib. 1, Pg. 432 H. Fluharty 7/12/77
Set 5/8" x 18" Re-Rod
Lib. 1, Pg. 441 P. Laphan 11/10/77
Set 1/2" capped Re-Rod
Lib. 4, Pg. 1175 G. Gray 4/27/92
Found capped Rod on centerline Baseline Rd.

4) Survey of Record
Lib. 3, PG, 604
Lib. 4, Pg, 312

REMONUMENTATION PEER GROUP Lud William E. Ruddell, PS County Representative

ACCEPTED BY THE ISABELLA COUNTY

WITNESS NOTE: Witnesses from above surveys and LCRC's are available in Dossier file; which was presented to peer review committee and is on file at the Register of Deeds Office.

B: Description of corner evidence found and/or method applied in restoring or reestablishing corner:

REPORT OF FINDINGS

In a field survey on December 29, 1994, excavated and searched for the corner location

- 1. Found capped 5/8' re-rod (set by H. Fluharty) and 1/2' rod (set by P. Lapham).
- 2. Removed found items and excavated 3' diameter hole to depth of
- 3. Found no further evidence of corner.
- 4. Set standard Isabella County Monument on line from SE. Corner to S.1/4 Corner Section 33, T.15N.-R.4V. at the G.L.D. call distance of 16.5 feet (25 Lks). Established position is 1.0' North of found corners by Fluharty and Lapham.

eplace.
Ing on No
A to
Of MICHO
S. Accepted as best available evidence of the position of the original corner & replaced with Standard Monument Corner G-1 was approved for remonumentation at a Peer Review Committee meeting on November 3, 1994.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set standard Isabella County Monument in Monument Box,

S.30°E. 66.03' Top center telephone cable box.
N.35°W. 57.38' LSC tag in W. face P.P.
S.32°E. 48.92' Stop sign post.
S.15°E. 72.60' Drange "+" in top East end 15' cmp road culvert.
S.21°W. 70.64' Drange "+" in top West end 15' cmp road culvert.

Signed by

Date

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED HAY: 1975 PLYSED JAN. 1583

No.

Michigan License No. 21567