SUMVEY & REMONUMENTATION

MAY 0 5 1997

COMMISSION

116501

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For Corners in _Isabella	Isabella County Remonumentation			
(County)	Located In:	Corner Code#;		STATE OF MICHIGAN COUNTY OF ISABELLA RECEIVED FOR RECORD
1. Public Land Survey	T. 16 N.R. 4 W.	<u>C-12</u>		NE CETYET THE RECORD
2. Public Controlling S	TR TR TR.			Dec 2600125 AM '96
in Section S. 3. Miscellaneous S. Property in Section S.	TR			REGISTER OF DEEDS
A T -431	ecorded Plat		Register of	Deeds Stamp & File Number

kens, in a field survey on Oct., 1996, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Professionals or by a Decree of a Court of Law, established, reestablished, monumented, recovered, found as expressed below.

NOTE: Not more than 2 corners, all in the same fown and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent
 - 1. Original G.L.O. Survey: Township lines Second Quarter 1837 John Hodgson Subdivision & Re-survey Second Quarter 1850 by William A. Burt Page 358 original field notes
 - 2. County Survey Records: Liber 2, Page 195 Joseph A. Graham September 5, 1882
 - 3. L.C.R.C : None

4. Surveys of Record:

None

5. Unrecorded Surveys:

LSC files - Section subdivision

Isabella County Road Commission - Section Corner Map

18

19

30

16

28-27

22

23

26

ACCEPTED BY THE IRABELLA COUNTY

GROUN

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Found 3/4" pipe This corner established in Isabella County Remonumentation Program. See dossier for detailed report.

1. Found 5/8" x 18" capped re-rod at 0.10' deep

2. Excavated to depth of 3.5'. No evidence of further material

Accepted as best available evidence of the position of the original corner & replaced with Standard Monument Corner C-12 was approved for remonumentation at a Peer Review Committee meeting on December 3, 1996.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set Standard Isabella County Monument in Monument Box. N.76°E., 34.40', Chiseled + on top of N. end of headwall

S.82°E., 39.04', Set L.S.C. nail and tag on top center of square fence post

N.58°W., 17.26', Chiseled + on top S. end of headwall

N.25°W., 28.78', Found LSC nail and tag on top center of fence post

FOKENS LAND SURVEYOR

Date

GAN STATE BOARD OF LAND SURVEYORS, JAN.28, 1971

Signed by Surveyors Michigan License No.

> VISED MAY 14, 1975 REVISED JAN., 1983 REVISED OCT, 1995