MAY 0 5 1997

116505

Filing Requirement of Act 74, Mich. P.A. 1970 Isabella County Remonumentation

Isabella County Remonumentation	
For Corners in	STATE OF THE
<u>Isabella</u>	STATE OF MICHIGAN
(County) Located In: Corner Code#:	RECEIVED TO RECORD
1. Public Land Survey T. <u>16 N.R. 4 W.</u> D-12 T R	0001 \$ 62 HIT '96
T R	SHARON A PREGIST A REGISTER STATE OF Deeds Stamp & File Number
I. Jan S. Fokens, in a field survey on Oct.,1996, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Professionals or by a Decree of a Court of Law, established, reestablished, monumented, recovered, found as expressed below. NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	1ABCDEFGHIJKLM 2 6 5 4 3 2 1 3 4 7 8 9 10 11 12 5 4 4 7 8 9 10 11 12 5 4 5 4 5 14 13 7 4 7 8 9 10 11 12 5 10 10 10 11 12 8 19 20 21 22 23 24 9 4 10 30 29 28 27 26 25 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
A. Description of original monument and accessories and/or subsequent restoration:1. Original G.L.O. Survey:	12 31 32 33 34 35 36
Township lines Second Quarter 1837 John Hodgson Subdivision & Re-survey Second Quarter 1850 by William A. Burt Corner not set in original survey 2. County Survey Records: Liber 2, Page 195 Joseph A. Graham September 5, 1882 3. L.C.R.C.: None 4. Surveys of Record: Liber 5, Page 467 Set re-rod and LSC cap 5. Unrecorded Surveys: None	REMONUMENTATION PEER GROUP ON 12 3 5 6 William B. Ruddell, P3 County Representative

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
This corner established in Isabella County Remonumentation Program. See dossier for detailed report.

1. Found re-rod with LSC cap

Corner was set at intersection of straight lines ran from established opposite quarter section corners. Replaced found LSC re-rod and cap with Standard Monument Corner. D-12 was approved for remonumentation at a Peer Review Committee meeting on December 3, 1996.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set Standard Isabella County Monument in Monument Box.

S.21°W., 22.70', Found nail and disc in 8" Poplar tree S.06°E., 18.07', Found nail and disc in 9" Poplar tree

S.27°E., 11.98', Found nail and disc in 10" Poplar tree

S.80°E., 1.52', Found nail and tag in E. face of 12" Poplar tree

JAN S. FOKENS

A. T.

Date _____

SURVEYORS, JAN.28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

AND

Signed by Surveyors Michigan License No. 21567