JACKSON COUNTY									
P.A. 345 of 1990	Center of S	ection 36, Leoni Township	LIBER	: 14	50	PAGE	738		
hairman Dem Suthamet	-	RECORDATION CERTIFIC							
Date Dec. 20, 1994	Filing Requirer	ment of Act 74, Mich. P.A. 1	970		CTATI	E OF MI	rcutcak	t.	
For corners in		_				CKSON (ī	
JACKSON Lo	ocated In:	Corner Code #				RECORI	DED		
	1s R 1E	L-12			28 DE(C 94 9	9:55 A.	.м.	
T, Public Land Survey	R								
T	R	<u>SURVEY</u> & REMONUMENTATION	ď			LD J. M ISTER (
2. Property Controlling S T	R [REMONUMENTALION	À						
in Section S T 3. Miscellaneous S T	R	MAY 0 3 1995							
Property in Sec. S T	R		Register	of Do	eds S	tamp &	ß File I	Numbe	er
4. Lot No, Recorded Pla	ıt	<u>COMMIS</u> SION	, <u>A</u>	В	C D	E F G	Э Н !	J K	L
5. Private Claims			2	6 -	5	.4	3	2	1
			3 -		:				
I, David E. Erickson, in a field s	survey on Decem	ber 12 .19 94 .	4	7	8	9	10	11	12
do hereby certify that under requirements of P. in lines 1 and 2 above were in conforman	A, 74, Michigan P.A. of 1	1970, the corner points mentioned	5 -	18	17	16	15	14	13
current manual of survey instructions of the Management or by a decree of a Court of Law	United States Departme	nt of the Interior, Bureau of Land	7		1	15			
above were in conformance with the rules of the Court of Law; established, re-established	ne Michigan Board of La	and Surveyors or by a Decree of a	8	19	20	21	22	23	24
expressed below:	,		10	30	29	28	27	26	2
NOTE: Not more than 4 corners, all in on this certificate.	the same town and ra	nge, may be recorded	11	<u> </u>	 				
A. Description of original monumer		diamanda and and and and and	12	31	- 32 -	33	34	35	•
government corner" as 990, Page 843.	a "concrete me	onument" per a certific	ate or	. su	Lvey	(0.0.	., <u>.</u>		, , , , , , , , , , , , , , , , , , ,
			٠,						
			· · · · · ·			v.	, e. d. y. ali t	7.00	
·		d applied in restoring or reestable			-				
dimensions. These two drainage ditch 6' deep of ditch. This monume Reestablished corner a	o points are base. Concrete movent was set from the control of th	1/4 lines and at loca sically the same and fal nument (as noted in Kell om incorrect corners and n of 1/4 lines. Set a cap in approximate cent y the same as was monument.	ll in t ler's s is no 60" a cerline	t ut Lumi:	enter y) fa ilize num p N-S (r of a alls o ed in oipe v drain	a nor on ea: this with age d:	th-so st sl surv stand itch.	uth ope ey. ard I
· ·		s established to perpetuate loca					er:		
1" x 60" Aluminum Pipe	with JCR Alumi	inum Cap stamped "L.S. 2	9245,	1994	, L-1	.2"			
N01°E Set Spike and	Tag 29245 in E	ast side of 14" Elm				8.89			
N13°E Set Spike and	Tag 29245 in No.	orthwest side of 16" Oak outheast side of 10" Oak	(1 oi	2)).05′ 5.62′			
N35°E Set Spike and			-		50	34'			
N86°E Set Spike and	Tag 29245 in S	outh side of 12" Cherry			31	L.19'	.		
N18°W Concrete Monus						OF M	Cy.	.	
Set County Surveyor si	ign post at NE :	side of JCR Cap		A. C.	SATE		A.C.	· N	
Note: Bearings are mag			-	*	El Lon	DA VI D RICKB Id'Surv	(Glacos, O66 E"	000	
Signed by Land E.	Euckson	Date Dece	embe		20	No. (2924	94		

ADAPTED ADAPTED TO

Surveyor's Michigan License No. 29245