LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY	T S., R V.	M-1, m-2	
2. PROPERTY CONTROLL- ING IN SECTION	,T S., R	M-1, M-2	
	,T N., R E.		
4. LOT NO , REC	CORDED PLAT		
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
the corner points mentioned field survey on	in lines 1 and 2 above (ider 19.74, established and in conformance with regularities States Department of e, that the corner points m found, recovered, restored, e	ntified with circles on index d, re-established, monuments alations and rules therefore a the Interior, Bureau of Land centioned in lines 3,4 and 5 established or re-established	P.A. 74, Michigan P.A. of 1970, code diagram – over) were, in a ed, re-monumented, recovered or s required in the current manual Management or by a decree of a above were, in a field survey on as expressed below and in contrs or, by a Decree of a Court of
A. Description of original mo	nument and accessories and	or subsequent restoration:	
549/2 W 1.	22 LINKS 24"R	ed Oak	
m-1 Set pos 549/2W 1. N 54W 1.	27 LINKS 23"	Elm	
m-2 Found 3" dia :	lid clay mon, set . with 2' Brass	by Bean in 1873. Cap. Set by Bean in	Popkred with 20 dia,
_		TON TOU TO CEPTIFY.	
n-1 20'dia, concré	te mon. with 2 di	c. Brass Cop.	ating the position of the corner:
589°E 60.57	ThornApple	North	56.19 14 Trpe Bosses
16087'36"E 50.0"	12'da Concreten	70N. 529 43 25"	50.0' 12"dia concretera
d dia concrete	man with 12 iron	west 66.0 East 66.0	
SURVEYOR'S MICHIGAN RE	GISTRATION NO.	,	(SEAL)
FOR STATE AND UNITED S	TATES AGENCIES:		
SIGNED BY	CHIEF OF SURVEY PARTY	DATE	
APPROVED AND SIGNED BY		DATE	
	MICHIGAN REGISTERED LA	ND SUNVETON	(SEAL)