## SURVEY & REMONUMENTATION

NOV 03 1999

| <b>CPPROVEO</b> | LAND CORNER         |  |
|-----------------|---------------------|--|
| P.A. 34         | ¥\$) of 1990, / / ∩ |  |
| Chairman 🔏      | of 1990             |  |

JACKSON COUNTY

5. Private Claims

**WEST 1/4 CORNER SECTION 18 RIVES TOWNSHIP** Date Aug. 13,1997 LAND CORNER RECORDATION CERTIFICATE

SECTION

| For comers in                   | comers in                                 |                                       |
|---------------------------------|---|---------------------------------------|
| _JACKSON                        | Located in: Corner Code #                 | #2057142<br>Liber 1558 Pase 537       |
| RIVES TOWNSHIP                  |   | Page 1 of 1                           |
| Public Land Survey              | T <u>1S</u> R <u>1W</u> <u>A-6</u><br>T R | Jackson Co., MI<br>Recorded           |
|                                 | T R                                       | 12/29/1997 10:27A                     |
|                                 | TR  | Minda Reilla                          |
| Property Controlling in Section | S TR<br>S TR                              | Register of Deeds                     |
| 3. Miscellaneous                | S TR                                      |                                       |
| Property in Sec.                | \$ TR                                     | _                                     |
|                                 |   | Register of Deeds Stamp & File Number |

Filing Requirement of Act 74 Mich D & 407

I, DAVID L. CLIFFORD, in a field survey on APRIL 24, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior. Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, requiremental recovered formation of the surveyors of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established. re-established, monumented, recovered, found as expressed below.

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

- 3 5 ΘÒ 7 9 10 26

- Description of original monument and accessories and/or subsequent restoration: MONUMENT NOT SET IN ORIGINAL GLO SURVEY.
  CONSUMERS POWER COMPANY USED CORNER AND STATED THEY USED IRON PIPE AND RECORDED 2 WITNESSES: 8" BLACK WALNUT 28.4" 12" BLACK WALNUT 35.80' S30W

3. ROAD COMMISSION USED CORNER AND LISTED 4 WITNESSES:

B. WALNUT 8" SOUTH 42.6" B. WALNUT 12" \$30W 54.3"

8" BLACK WALNUT 28 4

12" BLACK WALNUT 530W 45.3"

- SURVEYORS WORKING ON THE SUPER CONDUCTING SUPER COLLIDER SURVEY TRAVERSED TO CORNER IN JUNE 1988. MONUMENTATION USED WAS 1" SOLID BAR IN MONUMENT BOX.
- B. Description of comer evidence found and/or method applied in restoring or reestablishing corner:

  SEARCHED AT APPARENT LOCATION OF CORNER AND FOUND 1" SOLID BAR IN MONUMENT BOX 21.1" NORTH OF M-6 TOMPKINS 1"
  SOUTH OF NORTH EDGE OF WOOD ROAD. EXCAVATED THROUGH BOX AND FOUND NO FURTHER EVIDENCE OF A HISTORICAL NATURE. COMPARISON OF A SUPER CONDUCTING SUPER COLLIDER TRAVERSE INDICATED THAT BAR WAS ON STANDARD LINE AND MEASURED 2677.18" TO A-5 AND 2673.22" TO A-7. CONSUMERS POWER COMPANY WITNESSES ARE TO A 1/2" PINCH PIPE 12.6" SOUTH OF CORNER. ACCEPTED 1" BAR AS PERPETUATION OF CORNER AND REPLACED WITH CAST IRON MONUMENT.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. A-6 TISRIW

4" X 30" CAST IRON HARRISON MONUMENT WITH BRASS CAP STAMPED JACKSON COUNTY LS 25837.

SURVEY MARKER SIGN POST

NAZ 4° 6,2' NAZ 123° 113,39' NAZ 139° 76,10' NAZ 184° 21,10'

60D IN N.E. SIDE 35" WHITE PINE NAIL AND TAG 28409 W. SIDE 37" OAK

M-6 (STANDARD CONC. MONUMENT) NAIL AND TAG 28409 IN W. SIDE 29" WALNUT 60D SPIKE IN S.E. SIDE 22" OAK

NAZ 186° 41.17' NAZ 219° 50.40' NAZ 317° 91.91'

NAIL AND TAG 28409 IN W. SIDE POWER POLE

Daid Cuff 7 Signed by Surveyor's Michigan License No. 25837

Date <u>AUGUST 11</u>, 1997

OF MICHIEF DAVID CLIFFORD LAND SURVEYOR 25837 EAND

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975