

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


Jackson COUNTY  
T 1. South R 2. East

DESCRIPTION OF CORNER North West Cor. Sec. 10. T. 1. S. R. 2. E.

CORNER MONUMENT 3/4" pinched Iron Pipe

DATE MONUMENT PLACED AND WITNESSED Found & Witnessed 3-20-69

WITNESSES TO CORNER..... N. 52° E 34.2' Telephone Pole



S. 25° E. 25.4' 14" oak with P.K. nail & tag

N. 27° W. 40.4' 22" oak with P.K. nail & tag

AND  
East 26' Fence Cor. Post

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

WITH INFORMATION FURNISHED BY RICHARD GUTEKUNST.  
FOUND A 3/4" IRON PIPE IN APPROX. CENTER LINE OF  
PARKS ROAD. IRON PIPE SET BY RICHARD GUTEKUNST REG. LAND  
SURVEYOR #

4 | 3  
9 | 10

7/27/64  
"FOUND STONE, SET IRON IN TOP"

SURVEYOR'S SEAL

SIGNED

[Signature]  
REGISTERED LAND SURVEYOR

DATE

4/1/69

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing