

1-2-1966

N.E. QUARTER OF SECTION 5 T15R2E
 FOUND REMAINS OF OAK FENCE E-1
 POST IN GROUND BADLY ROTTEN
 HOLE SURROUNDED WITH STEAK
 SET 7' IN ON W. LINE
 WITH 1" LONG TO SOUTH E. END FENCE
 TO EAST. FENCE TO WEST IN
 VERY POOR SHAPE ALIGNMENT
 WOULD BE HARD TO DETERMINE
 EAST 8" HICKORY 46.1 NAIL SIDE
 5" 6" HICKORY 25.3 NAIL INSIDE
 W. N.W. 8" HICKORY 48.85 NAIL INSIDE

EAST 1/4 POST SEC 5 T15 R 2 E
 FOUND STONE WOOD STAKE
 SET 7' - 1820M
 40" OAK U.W 30° 38.9
 50" OAK S.W 30° 22.14
 70" OAK N. 20° 31.2
 IN LINE WITH FENCE

E-2

TEMPORARY N.W. CORNER OF
 SEC 6 T15 R 2 E
 1. 1/4 SECTION LINE WITH FENCE
 2. 1/4 SECTION SOUTH AND EQUAL DISTANCE
 3. OPEN ROAD FENCE,
 SOUTH FENCE POST 28.75' MAX E. SIDE
 S.S.E. EAST END STRUCTURE 66.2'
 SOUTH WEST END STRUCTURE 32.3'
 F.N.E. NORTH END STEEL TUBE 42.15' ^{JAN. 1966}
 (THIS TO BE MOUNTED 3.3' SOUTH H.W.D.)

