

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Jackson
(County)

Located In: Corner Code *11*

- | | | | | | |
|------------------------------------|---|----|---|----|----------|
| 1. Public Land Survey | T | 1S | R | 2W | G-4, G-5 |
| | T | | R | | |
| | T | | R | | |
| | T | | R | | |
| 2. Property Controlling in Section | S | T | R | | |
| | S | T | R | | |
| 3. Miscellaneous Property in Sec. | S | T | R | | |
| | S | T | R | | |

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

I, Donald L. Bissell, in a field survey on March, 19 89, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

| | | | | | | | | | | | | | |
|----|----|----|----|----|----|----|---|---|---|---|---|---|---|
| | A | B | C | D | E | F | G | H | I | J | K | L | M |
| 2 | 6 | 5 | 4 | 3 | 2 | 1 | | | | | | | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | 8 | 9 | 10 | 11 | 12 | | | | | | | |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | 17 | 16 | 15 | 14 | 13 | | | | | | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | 20 | 21 | 22 | 23 | 24 | | | | | | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | 29 | 28 | 27 | 26 | 25 | | | | | | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | 32 | 33 | 34 | 35 | 36 | | | | | | | |
| 13 | | | | | | | | | | | | | |

A. Description of original monument and accessories and/or subsequent restoration:

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- | | |
|--|--|
| G-4 E 1/4 Cor. Sec. 9 Found 1/2" ReRod In Asphalt Road | G-5 SE Cor. Sec. 9 3/4" I.P. in Mon. Box In Asphalt Road |
|--|--|

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- | | |
|--|--|
| G-4 E 1/4 Cor. Sec. 9 1/2" ReRod in Asphalt Road West - 5.4 - f Tompkins Road S46°W - 58.53' - 16" Maple S71°W - 41.36' - 14" Maple N48°W - 49.99' - 6" Poplar S84°E - 45.09' - 6" Maple | G-5 SE Cor. Sec. 9 3/4" I.P. in Mon. Box in Asphalt Road West - 4.5' - f Tompkins Road S44°W - 42.71' 12" W. Oak S26°W - 94.04' - 20" W. Oak S84°W - 47.18' - Twin Beech N33°W - 62.16' - 24" W. Oak |
|--|--|

Signed by Donald L. Bissell
 Surveyor's Michigan License No. 18655

