	JACKSON COUNTY APPROVED LAND CORNER P.A. 345 of 1990 Acting RenEm	WEST # POST, TOMPKINS TOWN	-		LIBER 1482 1	PAGE 641		
	Date 12-30-94	Filing Requirem	ent of Act 74, Mich. P	P.A. 1970	•			
	corners in		1		STATE	OF MICHIGAN		
1	JACKSON Loc	cated In:	Corner Code ##			SON COUNTY		
		3 0 0 11	4.10		Ş.	ECORDED		
1.	-	1 S R 2 W	A-10		17 ALIC	95 9:57 A.M.		
		R			11 HOD	70 7:01 Haffs		
					GERALI	J. McDEVITT		
					REGIS	ITER OF DEEDS		
				_				
		R R		Re	gister of Deeds S	tamp & File Number		
	•							
	Lot No, Recorded Plat				ABCDE	E F G H I J K L	М	
) .	Private Claims				2 6 5	4 3 2		
					3			
,			* Al.		4 7 8	9-10-11-12	4	
	DEAN R. GUTEKUNST, in a field sur ereby certify that under requirements of P.				5	- 	┨	
n lir surn fan sbov Sou	nes 1 and 2 above were in conformance ent manual of survey instructions of the U agement or by a decree of a Court of Law a ve were in conformance with the rules of the trule of Law; established, re-established, ressed below:	with regulations and ru Inited States Departmen nd/or that the corner po ne Michigan Board of La	ules therefore as required in the of the Interior, Bureau of pints mentioned in lines 3, 4 and and Surveyors or by a Decre	in the Land and 5 ee of a	6 18 17 7 8 19 20 9	21 22 23 24 28 27 26 25		
101	FE: Not more than 4 corners, all in t	the same town and r	ange, may be recorded		11		4	
	on this certificate. Description of original monument and	d accessories and/o	subsequent restoration	ı [.]	12 31 32	33 34 35 36		
	Post not set in original go		·	•				
	The second seco				Set average distant, Northwest corner to Southwest corner of Section 30,			
					fences agreei	_		
ľ	Not recorded in P. A. 74				Fireclay Post	t (3"Dia. x 24")		
} .	Description of corner evidence found	and/or method app	lied in restoring or reest	tablishing	corner:			
F L	Found FIRECLAY, 18" below to backhoe, starting under iron wide x 10' long and 4' d	olacktop, with on found in mon leep before find	broken brick belo ument box and exp ding fireclay.	ow. eanding	Excavated area to appr	with a coximately		
C	Corner is l½'±West of cente	r line of blac	ktop, and in line	of fer	nce East.			
F	Found iron in monument box,	1.5' South an	d 0.5' East of fi	reclay	, unknown ori	igin.		
C	Accepted FIRECLAY as a care corner, as ***monumented by Jackson County Monument and	Holcroft in 18	86. Replace	d fire	clay with a S	the original Standard		
i.	Description of monument for corner a							
	ste	el rod and an	ameter X 36" conc aluminum cap stam for Jackson Coun	ped LS				
	N 85° E 7" Cherry	50.25	40d & washer on	North	side	THE OF MICH	j,	
	S 15° W 14" Ash	70.74'	40d & washer on	South	east side	DEAN	1	
	S 10° E 27" Oak	130.62'	40d & washer on	West s	side	in R	. 7	
	S 30° W 23" W. Oak N 10° W 40" double		40d & washer on .35! 40d & washe			GUTEKUNST	, ,	
			.ככ. 40d & wash r sign attached	er on 1 20.0		No. 18658	4	

Monument box set over monument by Jackson County Road Commission.

18658

Signed by

Surveyor's Michigan License No.

December 29, 1994

Date.