JACKSON COUNTY LPPROVED LAND CORNER

SOUTH & POST, SECT SPRINGPORT TOWNSHIP SECTION 6

Date MARCH 2, 19	47 LAND CORE	NER RECORDATION CERTIFICATE	E	•
		uirement of Act 74, Mich. P.A. 1970	Ό	
For corners in JACKSON	_ Located In:	Corner Code ##		#2029643 Liber 1538 Page 53 Page 1 of 2
Public Land Survey	T 1 S R 3 W T R T R		NOITATION	Jackson Co., MI Recorded 03/13/97 <b>03:41P</b>
in Section 3. Miscellaneous	S T R	SECTION	N	Mindy Reilly Resister of Deeds Stamp & File Number
4. Lot No, Reco			2 6 5 3	E F G H I J K L I
Dean R. Gutekunst		7/29 96	4 7 8 -	
Court of Law, established, re-esexpressed below:  NOTE: Not more than 4 corne on this certificate.  A. Description of original more original Governments oak 10"	ners, all in the same town and accessories and ent Post set by Luci S 52 W 4 links	and/or subsequent restoration: cius Lyon, Deputy Surveyor, s (2.64°)	9 10 30 29 11 12 31 32 13 1 1925.	33 34 35 36
B. Oak 9"	S 71 E 30 links	s (19.80')		
Perpetuation by R Set iron pipe Mr Mart said it	t was the $\frac{1}{4}$ post)	's. of landside to plow (do not	: know who so	et it but a
Continued on back  B. Description of corner evide		d applied in restoring or reestablishing	a corner:	
Found 1" X 3.5' in Also found 8" piec	iron pipe, as descri	ibed above, 2" below gravel ar (landside of plow) along	l surface of gside of pip	pe.
Backhoe excavation has been cut appropriate and 1.7'	on of area revealed revinately 2'. West of corner.	no additional evidence of Also found a telephone	original con e cable burie	orner. Area led 2' below
Corner is approxi	mately in center li	ine of roads and in line wi	ith occupation	on Northerly.
. Accepted iron pipe position of the or	e and landside of poriginal corner, as	plow as a careful and faith remonumented by Riley in 1	hful perpetu: 1923.	lation of the
Sat a Standard Jac	ckson County Monume	ent, 6" below gravel surfacent and landside on the Sou	ce, and buri	ed the iron

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is a 4" diameter X 36" concrete monument with a ½" X 36" B-3 T1S, R3W steel rod and as aluminum cap stamped LS 18658, which is the standard monument for Jackson County.

**	North N 55° E S 80° E S 10° E	8" Cherry 20" Oak	64.0' 182.08'	found nail and 40d & washer on 40d & washer on	+0d & washer South side.	on South side.
	S 10° E North			sign attached		DEAN

Date Signed by .

18658

GUTEKUNST

Surveyor's Michigan License No. ...

Continued,

B-3 TIS, R3W

A.

```
* Double Elm 17" N 0 30 W 38.6'
Double Elm 15" S 84 30 E 133.61'
Y. Cak 18" S 13 00 E 107.60'
Y. Cak 22" N 42 00 W 107.45'
```

- Perpetuation by Consumers Power Company, Edwin J. McCombs, RIS # 10696, no date. Found iron bar, 5" down

Road sign post S 34 45 E 55.94'
34" Elm N 11 30 E 41.22'
Telephone Pole N 61 30 W 137.46'
Telephone Pole S 9 30 W 149.45'

- Perpetuation by Consumers Power Company, Perry McPherson, RIS # 12023, dated 1967. Found 1" pipe

\* 24" tree N 3 E 41.17'
Road sign S 35 E no distance
1' East of fence going North

- P.A. 74, recorded by Alan L. Scheppelman, LPS # 35998, dated October 11, 1994 in LCRC, Liber 4, Page 293, Jackson County Records.

1" pipe at intersection of roads East, South & Northwest

\* nail and tag in East side 30" stump North 39.48'

\*\* nail and tag in South side 8" B1. Cherry N 65 E 63.94'

Center line Road sign post N 25 W 29.10'

Genter line stop sign post S 35 E 62.55'