

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

W. Post Section 34 Leoni Twp.

FOR CORNERS OF	LOCATED IN -	CORNER CODE NUMBER	REGISTER OF DEEDS STAMP AND FILING NUMBER
1. PUBLIC LAND SURVEY	T. 2 S., R. 1 E.	G-12	2205
2. PROPERTY CONTROLLED IN SECTION	N. S., R. 1 E.		
3. MISCELLANEOUS PROPERTY IN SECTION	N. S., R. 1 E.		
4. LOT NO.	RECORDED PLAT		
5. PRIVATE CLAIMS			

Richard E. Gutekunst, RLS, do hereby certify that under requirements of P.A. 74, Michigan, P.A. of 1970 the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on December 9, 1972, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instruction's of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

W. Oak 7"	S16 W	245 links	Fireclay post about 4.0'
B. Oak 24"	N48½ E	238 links	south of E&W Ditch & 10' W of point where ditch turns
Tamarack 8"	N3 E	52 links	north.
Tamarack 7"	N38 W	36 links	
Maple 2"	S75 W	8.65 links	
Y. Oak 8"	S73 E	41.4 links	
Y. Oak 7"	N45 E	43.7 links	
Elm 10"	N40 W	46.5 links	

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Found fireclay. Set capped iron on N. Side, set metal post.  
Found iron 5.5' WNW.  $(\frac{3}{4} \times 5)$  Post about  $\frac{1}{4}$  South of  
E. & W. Ditch & Approx. 10' W of point where Ditch turns North

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

West	9" Oak	70.68'
W 5° W	6" Maple	18.82'
S 20° E	DBL. Maple	38.04'

SIGNED BY

*Richard E. Gutekunst*

DATE June 6, 1973

SURVEYOR'S MICHIGAN REGISTRATION NO. 7863

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY

CHIEF OF SURVEY PARTY

DATE

APPROVED AND SIGNED BY

MICHIGAN REGISTERED LAND SURVEYOR

DATE

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO.