PROVE LAND P.A. 345 of irman	1990	and N	orthwest (	Corner of Se	ction 36, Leor	ni Townsł	nin	LIBER	15(	)()	PAGE 1	170	
Date Dec					RDATION CER		•						
	•		Filing R	equirement of	Act 74, Mich. F	P.A. 1970							
For corners in JACKSON (Co.	unty)	ocated in:	Comer Code #			STATE OF MICHIGAN JACKSON COUNTY RECORDED							
1. Public Land	Survey	T <u>2S</u> T	R <u>1E</u> R	<u>K-11</u>					20 DEC	95 1	:00 P.I	1.	
Property Cor in Section     Miscellaneous			R R R R	PEM <mark>ONUM</mark>	NTATION						CDEVIT F DEEDS		
Property in §			R	FEB 2 2	1996	Register of Deeds Stamp & File Number							
5. Private Clain	ns			COMMISS	SION	<del></del>	16	B (	C D	E F	G H	J	L
							2	6	-5	4	3	2	
i , <u>David E, Ericl</u> do hereby certify the	hat under requi	rements of P.	A. 74. Michia	an P.A. of 1970 f	he comer points m	nertioned	4	7	8	9	10	П	E
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a						ed in the of Land	6	18	17	16	15	14	- 15
above were in con Court of Law; expressed below:	formance with	the rules of th	e Michigan I	Board of Land So	evenue or he a Da	cree of a	8	19	20	21	22	23	2
NOTE: Not more than 4 corners, all in the same town and range, may be recorded							10 11	30	29	28	27	26	2
· · • • •	certificate.						12	31	- 32	33	34	35	34
A. Description	n of original n	nonument ar	nd accesso	ries and/or subs	sequent restorati	on:	13 L	<u>.</u>	<u> </u>	<u>-</u>	<u> </u>		
Between 1886 a witnesses: "W. A corner witnes below blacktop. and re-measure	. Oak 14, S8: is card, date . Set iron ov	2°E, 41 1/4 ( d 10-24-69, ver 1/2° sq.	(27.22°)" ar obtained fi rod on top	id "Hickory 12, rom Gutekunst of F.C. to surf	, <b>S4 3/4°E, 393</b> 1 ! Surveyors, ind sce. Two old w	1/2 (259.71) licates the	)".	tor se	46.1 E	C	d : 1	) 9E	
B. Description	of comer ev	idence found	d and/or me	ethod applied in	restoring or rees	stablishina d	com	er.					
Found 1" x 18"   pipe. Found top Accepted Fire c 5/8" dia. x 36" id	pinch pipe in of Fire clay lay as a car	n Monumen directly be reful and fai	t box at Int low said P thful perpe	ersection Port inch pipe and stuation of the	age & Cain (We iron. Another o	st) Roads. old "iron" fo	Sec oun:	ond ' d on S					
					ed to perpetuate								
Set 5/8" dia. x 3 Existing monum	36" long reb ent box.	er with Jac	kson Cou	nty standard a	kuminum cap s	tamped "L	S <b>#</b>	29245	, 1995	, K-11	, T2S,	R1E"	in
	Top C/L @ Southwest Found Nail, Set Nail & T Southeast of Southeast of County Sur	corner GTE Southeast Sag, South scorner GTE Corner of ga	riser box: side R.R. t side Power riser box i rrage, Hous	ie post pole 11542	9 109 44.5 50.4 182 57.8 145. 25.5	51' 10' .26' 35' .10'			TE O	F MIC	Alcan.	<b>L</b>	
NOTE: Bearings	s are magnet	iic.					A STATE OF THE PARTY OF THE PAR	*	DA ERIC Land	VID E. CKSOI	yor )		
Signed by		£. E.		Dat	e <u>12-1</u>	3-95		E. E.	ED L	ND 9	URVETO	<i>F</i>	<u>.</u>
Surveyor's Michiga	an License N	lo	29245	FOR	MAPPROVED BY MICHIGAN	STATE SOARD OF	FLAMO	SURVEY	702 IAN 1				