STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

G-8

LAND CORNER RECORD

	DAUES DAI COUNTY
	τ <u> 25</u> <u>R</u> <u>IW</u> '
DESCRIPTION OF CORNER E 14 1	
CORNER MONUMENTSPIKE IN	PAVEMENT
DATE MONUMENT PLACED WITNESSED	10/9/69
WITNESSES TO CORNER	MAPLE NW 27.2'
NE Co	MAPLE NE 30.4' R. CONC. FOUNDATION OF HOUSE SW 78.2'
CIRCLE CORNER REGISTERED	
DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.	
WITHESSES FURNISHED BY CONSUMERS 10/9/69.	

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

REGISTERED LAND SURVEYOR

DATE Oct

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047 Rev. 10/68