## STATE OF MICHIGAN DEPARTMENT 0F **NATURAL RESOURCES**

## LAND CORNER RECORD

COUNTY

			Τ_	<i>2,5.</i>	R 1W	<del></del>
DESCRIPTION OF CORNER _	N. E. COR	. Sec. 2.	2			
CORNER MONUMENT 4" Cond	Mon With 1	Beass Cap.	In 17701	BOX E	Parne!	1 Rd.
DATE: MONUMENT REALISED_AND		/			<del></del> · · · · -	
VITNESSES TO CORNER	24" Elm	N. 04° W	! 29.6	<i>,</i>		
N22	26" Elm 48" Trip			······································	W. 48.	<u></u> 
CIRCLE CORNER REGISTER	ED .	· · · · · · · · · · · · · · · · · · ·			,	<del></del>

1-9 Jackson

Recovered 10-9-69 Set by others

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

SURVEYOR'S SEAL

DISTRIBUTION:

REGISTERED LAND SURVEYOR

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047 Rev. 10/68