


T. 2 S R. 2 E

Jackson Co.

SEC. 21



REMARKS

Found 1" Axle Shaft in place.

F-7

WITNESSES

8" Cherry - S 75° E - 80.61'
7" Elm - S 05° E - 84.28'


DELAMATER-MUSCHELL

Engineering and Land Surveying
Cheboygan, Michigan

G-7

T. 2 S R. 2 E

Jackson Co. SEC. 21



REMARKS

Found 2" Gas Pipe in place.

G-7

WITNESSES

24" Elm - N 37° W - 37.07'
12" Maple - S 60° W - 23.26'
30" Oak - S 08° W - 19.97'

DELAMATER-MUSCHELL

Engineering and Land Surveying
Cheboygan, Michigan

G-7