

JACKSON CO

③ S.E. Cor. of Section 13

2" Gas Pipe
 5" Maple N. 54° E 28.25'
 4" Maple S. 71° W 40.17'
 14" Willow N. 83° W 90.19'

M-7

MSHD 38103

MKW 11-24-58

④ N 1/4 Corner of Section 17

12" SPIKE
 22" Oak S. 84° W 22.66'
 7" Cherry N. 45° W 34.62'
 Cor. Post East 20.13'

D-5

MSHD 38103

MKW 11-24-58

⑦ N 1/4 Post of Section 18

B-5 FOUND 1" IRON
 8" 1/2" Tw. Oak N. 58° W 31.35'
 10" Oak N. 38 1/2° W 39.40'
 14" Hickory S. 65° E 28.30'
 10" Hickory S. 55° E 38.85'

IN LINE WITH FENCE WEST

COUNTY SURVEYOR'S OFFICE (REC. 6-22-58)

⑧ Sec. Corner Common to Sec 16, 15, 21 & 22

2" Gas Pipe
 24" Elm N. 37° W 37.07'
 12" Maple S. 60° W 23.26'
 30" Oak S. 08° W 19.97'

G-7

MSHD 38103

1960

⑩ Sec. Cor. Common to Sec. 15, 14, 22 & 23

1 1/2" Gas Pipe
 38" Oak S. 01° E 65.10'
 26" Oak S. 16° W 18.05'
 P.P. N. 59° W 73.12'

I-7

MSHD 38103

G.S.P.

1960

⑫ S.W. Cor. Sec. 16

Boat spike
 20" White Oak N. 33.45'
 12" Hick N. 45° W. 71.95'
 24" Red Oak S. 60° W. 66.15'
 16" Hick S. 45° E. 71.85'

E-7

D.H.W.

6-19-64

D.H.W.

⑬ S. 1/4 Post Sec. 16

3/4" Pipe
 10" Elm S. 24.40'
 13" Cherry E. 37.80'
 In fence E. W.
 In line with fence S.

F-7

D.H.W.

6-19-64

D.H.W.

⑭ W. 1/4 Post Sec. 16

1" Pipe
 8" Triple Wild Cherry S. 45° W. 21.20'
 10" Wild Cherry S. 10° W. 38.10'
 2" N. of old fence E. W.
 2" W. " " S.

E-6

D.H.W.

6-19-64

D.H.W.

⑮ S. 1/4 Post Sec 33

Mo. Box in place - 1957

F-13

⑯ Sec. Cor. Secs 20, 21, 28 & 29

1" AXLE SHAF.
 P. Pole South 31.56'
 Maple North 2.95'

FROM M.S.H.-D - 1956

E-9

MSHD COR. CORR. JULY-63 J.A.S.

MSHD COR. CORR. JULY-63 J.A.S.

⑰ N. 1/4 Post Sec 23

1" AXLE
 10" Elm N. 42° W 36.00'
 10" Elm N. 03° W 28.92'
 8" Birch S. 26° W 62.80'

I-26 R-22

Sec 31 & 2 A/20