STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

E-5 JACKSON COUNTY

T 2S R ~~1W~~ 2E

DESCRIPTION OF CORNER S.W. CORNER SECTION 9

CORNER MONUMENT FOUND 1" IRON PIPE WITH TOP BATTERED OUT TO 3"

DATE MONUMENT PLACED AND WITNESSED MARCH 7, 1970

WITNESSES TO CORNER..... S 75°30'W 12.19' 18" OAK



S 20°E 8.32' 16" OAK

N 07°E 55.18' SW COR. OF WOOD FRAME HOUSE

AND WEST 120.0' TO ℄ ROAD

CIRCLE CORNER REGISTERED S 75°E 13.31' 11" OAK

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

SURVEYOR'S SEAL

SIGNED _____ DATE _____
REGISTERED LAND SURVEYOR

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68