


STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

JACKSON COUNTY
T 25 R 2E

DESCRIPTION OF CORNER S 1/4 COR. SECTION 9
CORNER MONUMENT FOUND 1/2" IRON PIPE
DATE MONUMENT PLACED AND WITNESSED 3/7/70
WITNESSES TO CORNER..... EAST 52.0' E KATZ RD.



N 78°E 33.6' D.N.R. SIGN POST

N 77°E 26.9' 6" OAK P.K. NAIL N.W. SIDE

AND

S 32°E 10.25' 24" OAK P.K. NAIL EAST SIDE

N 86°W 26.20' 8" SASAFRASS

N 34°E 12.2' 6" OAK P.K. NAIL S.E. SIDE

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED _____ DATE _____
REGISTERED LAND SURVEYOR

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68