*	· VTML					
APTRON P.A	LAND CORN. 345 of 1999	IER		NON TO SECTIONS 30 POLEON TOWNSHIP		SURVEY &
Chairma	in Man 4	lebend			REN	MONUMENTATION
Dat	te <u>//-24-99</u>	ι	AND CORNE	R RECORDATION CERT		
•		<del></del>	Filing Require	ment of Act 74, Mich. P	.A. 1970	MAR 1 3 2000
For corr	nars in Jackson	Locate	ed In:	Comer Code #		
	(County)					SECTION
1. Pubi	lic Land Survey		3 <u>5</u> R1 E	<u>A-11</u>	<b>\</b>	
					(01991 11991 111 118991 1189 19	li 2139365
			R			Page: 1 of 1
O Bue	-artic Controlling		R	Mindy Reilly - Jackson	aranı (fadi (il adılı ile) il	12/08/1999 11:41A
	perty Controlling ection	s T	R		CO. CORREN	L-1818 P-1239
	pellaneous	sT	R			
	perty in Section	\$T	R		Register of D	leeds Stamp & File Number
4. Lot	No, Re	ecorded Plat_			A B	CDEFGHIJKL
5. Privi	ate Claims	<del></del>			2 6	╌┼╌╡╼┼╌╡╼┼╌┆╌┤╌┆╴
					3	<del></del>
Timo	thy B.				4 7	
i, VanG	ieson	in a field surve	yon <u>October</u>	<u>r 10</u> , 19 <u>98</u>	5	+ + + + + + + + + + + + + + + + + + + +
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the comer points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current						
manual of survey instructions of the United States Department of the Interior, Bureau of Land						
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a						
5 above Decree o	were in conformance to of a Court of Law; estab	with the rules o dished, re-estat	dished, monument	ed, re-monumented, recovered	d, found	
	essed below:				1030-	29 - 28 - 27 - 26 - 25
NOTE:		ners, all in the	same town and	range, may be recorded	12 -31-	32 33 34 36 36
	on this certificate.				13	
A. De	scription of original r	nonument an	d accessories a	nd/or subsequent restoration	on:	
A-11:	Original gove:			ebruary 09, 1829.	"78.01 ch. (5	,148.66') intersected
	"Wood Post"		00.31 (10.	1715		ks. (15.18') North of
	White Oak 30" White Oak 12"				post."	(Deputy Surveyor)
A-11:	Remonumentation		•	.20*)	May 04, 1825	(Deputy Surveyor)
T. T.	"Iron Post"	on (no da	re Procui			
	Yellow Oak 7"	N 25-1/4	° W 79 1ks.	(52.141)		ost at corner original Set fire clay post 2
	Cherry 3" S 8:	2-1/2° E :	57-1/2 1ks.	(37.95)	rods (33.001)	
A 41-	37 D 4 77/				John Holeroft	
A-li:	No P.A. 74 re-	cordings vidence foun	d and/or method	l applied in restoring or ree		•
A-11:		imp-pipe	15.5'± North	n of corner M-11, T	3S, RIW, as es	tablished by Dean R.
Gutekunst Registered Land Surveyor No.18658 and recorded in Liber 1540 Page 137. Hand						
dug at this position. Found 7" x 7" x 10" granite stone 0.5' below ground surface.						
Also found 3" (N-S) x 5" (E-W) x 17" sandstone 2.8' below existing ground surface.						
Sandstone matches record jog distance of 15.18' North of corner M-11, T3S, RlW, with Wes edge of stone falling on amended line of M-10, M-11, T3S, RlW.						
				d careful perpetuat		A-11.
						amended position.
				stacked on top of o nd surface. Left 5		t of monument at a
	and stones.	DCIO# CX	TSCTUE STOR	nd Sullace. Delt J	0.00 crimb-brhe	: Detween monument
C De	scription of monume	ent for comer	and accessories	s established to perpetuate	locating the position	n of the corner:
A-11;	4" X 36" conc	rete monu	ment with a	luminum cap R.L.S.		
	N 37° E 60-	d in East	side 26" 0a	ak -	47.83°	
			h side 26" (	Oak	34.43'	OF MICHIE
		e clay wi n post	tness post		33.16' 33.5'±	Est
		•	h side 22"	Cedar	58.91 <sup>1</sup>	TIMOTHY B. VanGIESON
				er M-11, T3S, R1W)	15.18'	쇼 LAND 가
	s 38° W 60-	đ in Norti	hwest side	twin 18" Oak	33.29'	SURVEYOR No. 24621
			side 24" 0:		24.64	
	À					PED IAND SU
	10/1	W .				Marie
Cia	by Timothy B.	VanGieson		Date	November 23	
aigri <del>e</del> 0	a wy					•

Surveyor's Michigan License No. 24621