JACKSON COUNTY PPROVED LAND CORNER											
P.A. 345 of 1990 South 1/4 Corner of Section 30.	-		SI	IBV	EY 8	<u>.</u>					
Date April 8, 1998 Filing Requirement of Act 74	, Mich. P.A. 1970	BEN	MON	ILIM	ENT	ÀTIO	N				
For comers in JACKSON Located In: Comer Code #			SEP 1 6 1998								
1. Public Land Survey T3S_R1EB-13	B-13				SECTION						
TR						Pag	8591 e: 1 a				
2. Property Controlling S T R	Mindy Reilly - Jack	son Co		CORRE	M	l i	5/1998 566 P				
Property in Sec. ST_R	Re	gister (of Dec	eds St	amp &	File N	umber	·			
Lot No, Recorded Plat Private Claims		ı A T	ВС	: D (F G	F H ₹	J K	L N			
		2 3 -	6	5	4	3	2	1			
I David E. Erickson, in a field survey on February 10 19 97,		4 5	7	- 8	9	10	17	12			
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corne in lines 1 and 2 above were in conformance with regulations and rules therefor current manual of survey instructions of the United States Department of the interior	e as required in the	6	: 16	17	16	15	14	13			
Management or by a decree of a Court of Law and/or that the corner points mentioned above were in conformance with the rules of the Michigan Board of Land Surveyors Court of Law, established, re-established, monumented, re-monumented, re-	in lines 3, 4 and 5 or by a Decree of a	7 -	19	20	21	22	23	24			
expressed below:		9 10	30	29	28	27	26	25			
NOTE: Not more than 4 corners, all in the same town and range, may be recon this certificate.	corded	11	31	32	33	34	35	36			
A. Description of original monument and accessories and/or subsequents	ent restoration:	13 L	•					<u> </u>			
witness by M.S. Cook. Set post on stone to surface." and recorded "W. Oak 5, N59°E, 310" (204.60'). In 1976, R.E. Gutekunst - RLS #7863, recorded the corner as "Found Oak, 202.95'; N59°±E, 6" W. Oak, 204.60'; South, 4" Sass, 2.41'; N80 Corner Recordation Certificate (LCRC) recorded at Liber 2, Page 56 A Corner index card of Jackson County Road Commission dated Walnut, N.15°E., 58.17'; 18" Cherry, N.80°E., 16.73; 18" Walnut, S.10	I Fireclay and Iron' 0°±E, 24" Cherry, 1 3. 1984 reports "Fire	' and li 6.36'; :	sts 5 \$10°±	witnes E, 18" and lis	sses: ' 'Ash, '	"N78° <u>1</u> 30.25''' witness	E, 20** per La	W. and			
B. Description of corner evidence found and/or method applied in res				.,	•, ••••						
Found fireclay (FC) with a 1" pinch pipe on the North side. Accept corner. Set a standard Jackson County concrete monument at monument.	ted FC as a careful exact location of	l and fo	aithfu FC.	Burie	d FC (on We	ne orig st side	inal e of			
C. Description of monument for comer and accessories established to					e come	er.					
Set 4" diameter x 36" long concrete monument with cap stamped "		#2924	5, 199			_					
North Set nail and tag #30087, East side 9" Sassafras N 77° E Set nail and tag #30087, Northwest side 24" Cherry S 16° E Set nail and tag #30087, East side 4" Sassafras S 02° W Set nail and tag #30087, West side 20" Ash	19.30' 16.26' 2.30' 29.93'	DAVID E									
NOTE: Bearings are magnetic	,, —		AND AND THE PARTY OF THE PARTY		AICKSO nd Survi No. 29245 LAND	eyor SUR	TOR AT				
Signed by taul auchan Date	4-7-	70					·				

Surveyor's Michigan License No. 30087