Jackson Count. Approved Land Core	±# ["\									
P.A. 345 of 1990 Chairman Date April 9,19	Southwe	est Corner of Section CORNER RECORDATION Requirement of Act 1		ip			Page	1540 1) Page of 1)., MI	
For corners in JACKSON (County)	Located In:	Comer Code #	SURVE REMONUME		~! ^!	N f	Record 04/10 Minds	rded 1/97 (: Reil)8:27A	À
Property Controlling in Section Miscellaneous Property in Sec.	T R T R T R T R T R T R T R T R T R T R		APR 28	1998 N J iste r	of De	eds St	tamp &	. File N	umber	
Lot No, Records Private Claims	10 Field			2 2	6	5 5	E F (3	2	1
I David F Frickson in a	a field survey on Jan	uary 24 , 19 <u>97 ,</u>		4	7	8	9	10	11	12
I, David E Erickson, in a field survey on January 24 19 97. do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as					18	17	16	15	14	13
					19	20	21	22	23	24
expressed below:		own and range, may be re		10	30	29	28	27	26	25
on this certificate.		essories and/or subsequ		12	31	32	33	34	35	36
 A. Description of original 	al thoughteen and acce	Section with a parade		13 L						

Around 1825, H. Parke - Deputy Surveyor, set a "Post" and recorded two witnesses: "Y. Oak 14, S66°W, 21" (13.86') and "Y. Oak 20, N54°E, 26" (17.16').

Around 1888, H.F. Bean reported "post and one good Witness standing and found remains of the other witnesses." and recorded two witnesses: "Hickory 18, N7 1/2°E, 99" (65.34') and "Y. Oak 6, N54 1/2°W, 31 1/2" (20.79').

In 1972, F.E. Spicer - LS #7877, recorded the corner as "1/2" iron in blktp accepted as cor" per a Land Corner Recordation Certificate (LCRC) at Liber 1, Page 149.

In 1980 and again in 1990, R.W. Keller - LS #20707, noted the corner as "Found iron & Fireclay" per a Certificate of Survey (COS) at Liber 989, Page 304 and Liber 1384, Page 22.

B. Description of comer evidence found and/or method applied in restoring or reestablishing comer:

Found bottom 12" of Fire Clay (FC) down 1.8 feet with a 1" iron pipe (IP) on North side and a 3/4" rebar on the South side. Found several pieces of pottery around base of FC. Also found a 1" IP in centerline of Page Avenue. The pipe would seem to be the position recorded by Spicer. This IP is rejected as the corner because its erroneous. Accepted found FC as a careful and faithful perpetuation of the position of the original corner as remonumented around 1888. Replaced FC with a standard Jackson County concrete monument. Buried pottery around base, FC on North and Irons on South side of monument.

C. Description of monument for comer and accessories established to perpetuate locating the position of the comer:

Set 4" diameter x 36" long concrete monument with cap stamped "1997, LS #29245, G-3, T3S-R1E".

N 04° E	Found 1" pipe in Page Avenue centerline (Probable point recorded by Spicer)	30.59'
N 20° E	Set nail and tag #29245, Northwest side 14" Maple	71.95'
N 73° E	Set nail and tag #29245, South side 24" Oak	148.29'
N 64° W	Set nail and tag #29245, North side power pole	23.95'
N 42° W	Set nail and tag #29245, Northeast side 26" Oak (Keller = 78.75')	78.69
S 38° W	Northeast corner, House	71,11'
South	County Surveyor sign post	1.0'

29245

NOTE: Bearings are magnetic

Surveyor's Michigan License No.

DAVID E.
ERICKSON
Land Surveyor
No.
29245
See LAND SURVEYOR
RECORD SURVEYOR
RE

Signed by Land E. Cucken Date 4-8-97

ORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1871

REVISED MAY 14, 1975 REVISED JAN., 1943 PROCESSING MARCH, 1983