P.A. 3	LAND CORNE	SE CORNER, SEC	TION 18, SPRING ARBOR	TOWNSHIP	
Chairman +	, , , , , , , ,	LAND CORN	ER RECORDATION CERTIF	ICATE	
Date _	NOU-13, 1996	`	rement of Act 74, Mich. P.A		
or corners in	· !	i imig riequii	rement of Act 14, Mich. F.A	. 1970	#2022273
Jackson	n	Located In:	Corner Code ##		Liber 1533 Page 170
(C	ounty)	Located III.	Comer Code		Page 1 of 1
		20 214			Jackson Co., MI
 Public Lar 	nd Survey	T 3S R 2W	C-7		Recorded
		T R			12/11/96 11:35A
	,	<u>T</u> R			Jerry McDevitt
O Dummandus C	Ozzatuskim u O	T R			Resister of Deeds
Property 0 in Section		TR			
3. Miscelland					
	n Sec S	T R T R		Register of Deed	ds Stamp & File Number
Property i	11 3 0 0.	n		<u> </u>	
4 Lot No	Record	ted Plat			
				A B C	DEFGHIJKLN
o. 1va.c o	usiiio			2 6	
				3	<u> </u>
_	_				
Alan L. a	Scheppelman	field survey on	June 3 96	5 5	8-1-9-10-11-1-12-
do hereby certif	y that under requirem	ents of P.A. 74, Michigan P.A	A. of 1970, the corner points mention	led	
in lines 1 and 2	2 above were in conf	ormance with regulations a	ind rules therefore as required in	the 18-	17
	-	•	irtment of the Interior, Bureau of La	1 I T	╂╌╂═╂═╂┈╂┈╂═╂═╂┈
· ·			er points mentioned in lines 3, 4 an of Land Surveyors or by a Decree o	~ 19+	20
		-	-monumented, recovered, found	21 1 1	
expressed belo	w:			10	2928272625
NOTE: Not n	nore than 4 corner	s, all in the same town a	and range, may be recorded	11	
	is certificate.		• • •	12	32 33 34 35 36
				13	
A. Description	on of original monu	ment and accessories ar	nd/or subsequent restoration:		
	CUS LYON, D.S.		OST CORNER - SECTIONS	17, 18, 19, &	20
MARC	сн 10-12, 1825	•	N14E, 60 LINKS (39.60		
		B. OAK 24,	S53W, 24 LINKS (15.84	')	
म . म	. BEAN	1 WITHWESE C	MANDING BOUND DOZUM		
	JUNE, 1886	AMALM CAHLU	TANDING, FOUND POINT (SS, J. OAK 24", N82½E,	OF STAKE & THE	REMAINS OF THE
	7 1000	OTHER WINE	BR. OAK 14", S51/2E,	1216 TINKS (13.	.86')
			BR. VAR 14 , 5545	, 1214 PINKS (30.19*)
R Description	on of corner eviden	ce found and/or method	applied in restoring or reestab	dishing corner	
b. Description	at of contenenders	ce lound and/or method	applied in restoring or reestar	manning corner.	
THIS	CORNER IS IN	A CULTIVATED FIE	LD AND NO OCCUPATION I	LINES WITHIN 60	001.
WILI	ARD LOUD IS T	HE CURRENT OWNER	OF PROPERTY IN SECTION	IS 17. 18. 19.	AND
20.	MORE THAN 20	YEARS AGO THE HE	DGE ROW WAS DUG OUT AN	ID THE STUMPS I	BURTED.
MR.	LOUD HAS 18"±	OF THE FIRECLAY	IN TWO PIECES IN HIS E	BARN. THE CORN	IER
POSI	TION WAS DOUB	LE PROPORTIONED F	ROM THE 1/2 CORNERS IN A	ALL FOUR DIRECT	TIONS.
SEE	SKETCH ON BAC	K. SET A STANDAR	D JACKSON COUNTY MONUM	MENT.	,
C. Description	on of monument for	corner and accessories	established to perpetuate loca	ating the position of	the corner:
A # ₹	. 364 GONODEED	MANIIMBUM WTMP	OFFICE CONTRACTOR		
4 A	. JO CONCRETE	A SECCO 1: 5	CKSON COUNTY REMONUMEN	TATION CAP STA	MPED
N47°		O. 35998", 1' BEL			AND THE PARTY.
N51°			SIDE OF 12" TWIN MAPLE		SINKE OF MICKY
иео.		TAG #35998 IN NW :		575.86	ALAMI Q
888°			SIDE OF 30" TWIN OAK TH SIDE OF 50" OAK	534.17	SCHEPPELMAN 7
200	— MITTH #	TIO HOUSE IN MOK	TH OTTHE OF DU" UNK	618.06	PROFESSIONAL *

SURVEYOR S No. 35998 06/24/96 Date 35998 FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983 Surveyor's Michigan License No. ____

1.

SPRING ARBOR TOWNSHIP - T35, RZW

