JACKSON COUNTY  APPROVED LAND CORNER  P.A. 345 of 1990  Chairman Land Lattane  WEST 1/4 POST, SECTION 21, SPRING ARI  LAND CORNER RECORDATION CER  Filing Requirement of Act 74, Mich.  or corners in	RTIFICATE Liber 1532 Page 412
JACKSON Located In: Corner Code #	Reconded 11/26/96 02:07P
(County)	Jerra McDevitt
Public Land Survey  T 3S R 2W E-8  T R  T R  T R  T R  T R  IN Section  S T R  Miscellaneous  S T R	Register of Deeds
Property in Sec. S TR	Register of Deeds Stamp & File Number
MICHAEL A GROAT , in a field survey on OCTOBER 7 , 19 sereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in and 2 above were in conformance with regulations and rules therefore as required in the current masurvey instructions of the United States Department of the Interior, Bureau of Land Management or by a few account of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformant the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established.	lines 1
e-established, monumented, recovered, found as expressed below:	B 19 20 21 22 23 24
Not more than 2 corners, all in the same town and range, may be recorded on this certificate.  Description of original monument and accessories and/or subsequent restoration:	9 10 -30 -29 -29 -27 -26 -25 11 12 -31 -32 -33 -34 -35 -36 13
DRIGINAL SURVEY, 1825 BY LUCIUS LYON, DEPUTY SURVEYOR, SET POST, N 14° E, Y. OAK 3½ LINKS; SOUTH, WHITE OAK, 12", 32 LINKS.	C 12",
H.F. BEAN, JUNE 12, 1886, FOUND POST AND TWO WITNESS STANDING, Y. OAK, 12" N 14° E	E, 131/2 LINKS; W. OAK, 12", SOUTH 32 LINKS
RICHARD E. GUTEKUNST, RLS #7863, IN LCRC DATED FEBRUARY 26, 1975 AND RECORDED CAPPED IRON ON NORTH SIDE, N 85° E, 20" Y. OAK, 19.04"; S 40° W, 24" W. OAK, 31.80"; N 5° HICKORY, 10.44"	IN LIBER 2 ON PAGE 575, FOUND FIRELCAY AND SET A ¾" E, 18" Y. OAK, 12.10"; S 10° E, 6" HICKORY, 17.0"; WEST, 6"
3. Description of corner evidence found and/or method applied in restoring or reestable found A ½" PIPE AND A ½" PIPE BENT OVER, MEASURDED FROM GUTEKUNST WITNESSE PIPES AFTER THEY STRAIGHTEND OUT. EXCAVATED AND FOUND OLD BRICKS BENEATH MONUMENT IN PLACE OF FIRECLAY.	S AND DUG. FOUND 3" FIRECLAY ON SOUTH SIDE OF
Description of monument for corner and accessories established to perpetuate local	iting the position of the corner:
BET A 4"X36" CONCRETE MONUMENT WITH 1/4" RE-BAR AND JACKSON COUNTY CAP, STAM	PED 'E-8 T3S R2W P.S. #39079'
EAST, NAIL IN SOUTHERLY SIDE OF 24" OAK, 19.00" PS° NAZ, NAIL IN SOUTHEASTERLY SIDE OF 22" OAK, 28.00" PVEST, NAIL IN SOUTHERLY SIDE OF 8" HICKORY, 31.22" P17° NAZ, NAIL IN NORTHWESTERLY SIDE OF 28" OAK, 31.65" FORTH, NAIL IN EASTERLY SIDE OF 15" WHITE OAK, 22.5" FORTH, NAIL IN EASTERLY SIDE OF 15" WHITE OAK, 22.5" FOURVEY MARKER SIGN, NORTH, 14.5"	CODAT COMMAND
HAZ = AZIMUTH MEASURED FROM MAGNETIC NORTH	tio.
Signed by Muchael A. Sroa	Date NOVEMBER 8 1998
Surveyor's Michigan License No. 39079	CE 53101
971	PPROVED BY MICHIGAN STATE BOÄRD OF PRÖFESSIONAL SURVEYORS, JAN. 28, REVISED JAN., 1983 REVISED OCT., 1996