JACKSON COUNTY	1/4 CORNER CO	MMON TO SECTION	NS 27 & 28			
P.A. 345 of 1999	a Spri	ing Arbor Township	NO 27 & 20			
Chairman Lank Leidhe	met	g				
Date Dice. 13, 1995		RECORDATION CERTIF	FICATE			
	Filing Requireme	ent of Act 74, Mich. P.A	ı. 1970			
For corners in	cated In:	Corner Code #				
(County)						
			LIBER 1509 PAGE 1068			
Public Land Survey	[™] 3S R 2W	-6-10	LINES & LINE BE & C. LINES BE A SEC.			
	T R T R					
	T R					
2. Property Controlling S	_T R					
	_T R					
	_TR		Register of Deeds Stamp & File Number			
Property in Section S	_T R		riegister of Deeds Stamp & File Number			
4. Lot No, Recorded Pl	lat	<u>'</u>				
5. Private Claims			A B C D E F G H I J K L			
			2 - 6 - 5 - 4 - 3 2 - 1 -			
			3			
IFred N. White in a field survey on November 25 1995 5						
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned						
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current						
manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and						
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a						
Decree of a Court of Law; established, re-e	pund 5					
as expressed below:		·	10 30 29 28 27 26 25			
NOTE: Not more than 4 corners, all in on this certificate.						
			12 31 32 33 34 35 36			
A. Description of original monument	and accessories and/o	r subsequent restoration:				
Original Covernant Best -						
Original Government Post s N 67 1/2W, B. Oak 18*, 5	et by Lucius Lyo 6 Links (36 96 F	n, U.S. Deputy Sur	veyor, March 1825.			
S14E, B. Oak 24", 40 Lin	•	eec,	STATE OF WICKISM			
Perpetuation by H.F. Bean	Janson Colney					
S17E, Br. Oak 20", 80 L	recoret					
N80 1/2°W, Br. Oak 24", 107 Links (70.62 Feet)						
Set 3" x 24" Fireclay			28 FEB 96 2:41 P.M.			
CONTINUED ON O	THER SIDE		GERALD J. MESEVITT			
B. Description of corner evidence for	und and/or method app	olied in restoring or reesta				

Found 3/4" pipe with cap #7863 in North-south fence line excavated & found fireclay at 1.3 feet & a second fireclay at 2.5 feet directly under the 3/4" pipe. Removed both fireclays and 3/4" pipes and accepted the position of the deepest clay. Set 4" \times 36" concrete monument with 1/2" rebar and Jackson County Cap.

\$ 2.00 REMONUMENTATION \$ 9.00 CORNER REMONUMENTATION

٠.	Description of monument for corner	and accessories established	to perpetuate locating tr	e position of the corner:
			-3	i .

4" x 36" CONCRETE MONUMENT AND JACKSON COUNTY CAP STAMPED "G-10 T3s R2W LS NO. 12034"

S57°W Nail & Tag #12034 Northwest Side, 6" Elm, 17.73'

S73°W Nail & Tag #12034 Southeast Side, 6" Hickory, 18.48'

S44°W Nail & Tag #12034 Northwest Side, 15" Maple, 55.09'

S23°W Nail & Tag #12034 Northeast Side, 12" Maple, 30.00'

N15°W Nail & Tag #12034 East Side, 6" Elm, 16.76'

N35°W Nail & Tag #12034 Southwest Side, 15" Cherry, 27.60'

N41°E Nail & Tag #12034 Northwest Side, 4" Elm, 32.24'

Steel Fence Post North 1.0±

FRED N.
WHITE
LAND SURVEYOR
NO. 12034

Date NOVEMBER 27, 1995

Surveyor's Michigan License No. 12034

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:
L.C.R.C. by R.E. Gutekunst #07863, March 31, 1975. Recorded in Liber 2, Page 582
'Found Fireclay 8" below surface with stone and old plow point around. Set 3/4" x 18"
capped iron 12" below surface on Northeast side fireclay. Set 3/4" x 4' capped iron on North side fireclay - with top of iron over fireclay.'

South 4" Hick 96.38' \$40°W 12" Hick 53.78' N35°W 4" Hick 27.99' N40°W 28" Oak 63.78' N60°W 28" Oak 77.30'

N15°W 6" Hick 73.0