JACKSON COUNTY APPROVED LAND CORNER Acting Chairman	SOUTHWEST CORNER, NORVELL TOWNSHIP	, SECTION 34	SURVEY & REMONUMENTATION
Date 9-9-98	LAND CORNER REC	ORDATION CERTIFICA	
	Filing Requirement	of Act 74, Mich. P.A. 19	JAN 2 7 1999
For corners in JACKSON	•		JAN # 1 1353
(County)	Located In: Co	rner Code ##	SECTION
Public Land Survey	T 4 S R 2 E	G-13	
in Section S 3. Miscellaneous S	T R	Mindy Reilly - Jackso	2089646 Page: 1 of 2 18/05/1998 10:580 L1582 P-422 Register of Deeds Stamp & File Number
4. Lot No, Recorded P			- ABCDEFGHIJKL
5. Private Claims			
in lines 1 and 2 above were in conforman current manual of survey instructions of th Management or by a decree of a Court of La above were in conformance with the rules of Court of Law; established, re-established expressed below: NOTE: Not more than 4 corners, all	ice with regulations and rules the United States Department of the United States Department of the wand/or that the corner points mother Michigan Board of Land States, monumented, re-monument	nerefore as required in the he Interior, Bureau of Land nentioned in lines 3, 4 and 5 preyors or by a Decree of a ted, recovered, found as	3 3 4 7 3 9 10 11 12 5 6 13 17 16 15 14 13 7 8 19 20 21 22 23 24 9 10 30 29 28 27 26 25 11
on this certificate.			12 31 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent restoration: Original Government Post set by Hervey Parke, Deputy Surveyor, 1824. NOTE: Post & bearing trees for corner of Section 33 & 34, Omitted. Perpetuation by Benj. F. LaRue, successor to H. F. Bean, Jan. 1885. Y. Oak Dbl. 10" N 34½ E 32 links (21.12') Located corner of 3 & 4 of W. Oak 8" N 81 W 109½ links (72.27') 5 S, 2 E from a blazed stump c W. Oak 6" S 31½ W 122½ links (80.85') wit (N.E.). Then located this corner 46 links E. This corner as located by intersecting line between ‡ post E & W wit line of ‡ post and Section corner N. would be N 56 W 19 from post. Drove stake at the other place. Continued on back,			
B. Description of corner evidence for		-	ing corner:
Found large top firecl	ay, broken in 4 piec	es, no bottom, ov	er brick.
Accepted fireclay as a original corner.	careful and faithfu	1 perpetuation of	the position of the
Set a Standard Jackson	County Monument and	left fireclay bu	ried beside monuments Michigan
Corner is 35' East o			DEAN GUTEKUNST No. 18658
C. Description of monument for corne	er and accessories establish	ed to perpetuate locating	the position of the corner
G-13 T4S, R2E Corn and Jack	er is a 4" diameter	X 36" concrete mo	nument with a $\frac{1}{2}$ " X 36" steel roch is a standard monument for
S 45*W 8" Hickory S 75**W 7" Walnut N 48**W 1½" Maple West Found iron i East Found capped S 40 W Axle Shaft S 60*W Steel post a	95 65 172 n blacktop of Pink S	147' 117' treet 30.36' 75'	center line, no nail center line, no nail center line, no nail corner 324, T5S, R2E
	fence post 62.64) Date N	26° E 3" Steel fence post
Surveyor's Michigan License No.	an Later Lute Burn	- له	tember 1, 1998 Prolyes by Michigan State Board of Land Subveyors, Jam. 28, 19 Revises May 14, 19

AN STATE BOARD OF LAND SURVEYORS, JAM. 28, 19 REVISES MAY 14, 19 REVISED JAM., 19

Continued,

A.) Perpetuation by the Jackson County Road Commission, no name, no date. Fireclay 6" deep.

Buggy Axle 2' above ground

10'S, of E & W fence -- 10'E of N & S fence

14" Twin Maple S8W 90.9'
12" Sassafras Center of group of 6 trees N 86-30 E 85.4'

- Not recorded in P. A. - 74

L-1582 P-422

SURVEY & REMONUMENTATION

JAN 27 1999

SECTION